

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
LONPAC INSURANCE BHD			Ref : CS3/LPC19008316/Evf3n2-1		
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date: 04-11-2020 Code: LPC2			
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	XD 6994L	Veh. Inspected	GBD 2894D	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	19/19/19/VC05/021748	Excess (\$)	0.00	
	Assign From	ONG LI LI	Assign Date	02/11/2020	
2. Vehicle Particulars & Condition					
	Make & Model	NISSAN CABSTAR	c.c	2953	
	Engine No.	HIDDEN	Year of Reg.	2014	
	Chassis No.	JN1SC2F24Z0856245	Colour	WHITE	
	Odometer	180392	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	FAIR			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	175 R15C	BRIDGESTONE	5 mm	
	L/H Front Tyre	175 R15C	BRIDGESTONE	5 mm	
	R/H Rear Tyre	175 R15C	BRIDGESTONE	5 mm	
	L/H Rear Tyre	175 R15C	BRIDGESTONE	5 mm	
4.					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	02/05/2019	Inspection Date	10/05/2019	
	Survey held at	N-51 AUTOMOTIVE PL			
		2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORI	ESTIMATED NORMAL PERIOD FOR REPAIR: 7 Working Days			