

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969

Our Ref : 305431007
Date : 02-11-2020
Time of Fax: _____

Via Fax : EMAIL
Your Insured: SLG 4898X
Date of Acc : 31-10-20

Attn: Motor Claims Department

ALG

Dear Sirs

SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO. SH 6607 T

Our client has engaged us to repair the above vehicle and submit claims against the other party/parties-involved in the accident _

In accordance to the motor claims framework, we hereby request your presence at 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.

Enclosed, please find:

- i) Our initial estimate of repairs of the damaged vehicle;
- ii) Accident report made by our client.

I would appreciate it if you could call us to arrange for the survey of the vehicle:-

♦ Lim Kwok Eng	Tel: 6214 8316 or HP: 9824 0811	} jumanibm@cdge.com.sg Fax no. 6546 8156
♦ Jumanibm Masudin	Tel: 6214 8315 or HP: 9635 5305	
♦ Lim Tien Siong	Tel: 6214 8398 or HP: 9635 8546	
♦ Chiang Liat Choon	Tel: 6214 8314 or HP: 9296 6006	
♦ Larry Ng Nyuk Phin	Tel: 6214 8315 or HP: 9230 2824	
♦ Fauzy Bin Mokhtar	Tel: 6214 8319 or HP: 8125 9176	

→ If we do not hear from you within the next 48 hours, we shall deem that you have waived your rights to survey our client's vehicle and we shall proceed to engage independent surveyor without further reference to you. We henceforth reserve our rights to claim for Loss of Use and Loss of Rental during any delayed period of this survey arrangement.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

Thank you.

Yours faithfully

for Vice President
Crash Repairs & Claims Recovery

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305431407
REGN NO : SH 6607T
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 08.12.2016
DATE/TIME IN : 02.11.2020 11:20
ACCIDENT DATE : 31.10.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0579-G	I40VC COVER ASSY-RR BUMPE	1	1,106.00	20.00	884.80
0002 04-01-0103-0738-G	I40VC COVER-RR BUMPER LWR	1	228.00	20.00	182.40
0003 04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10 L	22.00	20.00	17.60
0004 04-01-0103-1150-A	I40VC PROTECTOR MAT	1 N	50.00	2.00-	50.00

SUB-TOTAL : 1,134.80

JOB NATURE

0000 PB	PANEL BEATING	300.00
0001 SP	SPRAYPAINT CHARGE	300.00
0002 L	REMOVE/REFIX REVERSE SENSOR	80.00

SUB-TOTAL : 680.00

TOTAL : 1,814.80

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :