

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

YLG (Lum)

Date: 02.11.2020
Time: 15:23:36
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305431407
REGN NO : SH 6607T
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 08.12.2016
DATE/TIME IN : 02.11.2020 11:20
ACCIDENT DATE : 31.10.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0579-G	I40VC COVER ASSY-RR BUMPE	1	1,106.00	20.00	884.80	X R
0002 04-01-0103-0738-G	I40VC COVER-RR BUMPER LWR	1	228.00	20.00	182.40	X
0003 04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10 L	22.00	20.00	17.60	X
0004 04-01-0103-1150-A	I40VC PROTECTOR MAT	1 N	50.00	2.00-	50.00	X

SUB-TOTAL : 1,134.80

JOB NATURE

0000 PB	PANEL BEATING	300.00	280
0001 SP	SPRAYPAINT CHARGE	300.00	200
0002 L	REMOVE/REFIX REVERSE SENSOR	80.00	X

SUB-TOTAL : 680.00

TOTAL : 1,814.80

MVA NAME & SIGNATURE
DATE : *2/11/20*

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

Steve (LKK)

M. Pal

2/11/20, 4.30pm

2 days

By AC sy

L/S

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: