

ASS. REC. BY:

REF: CTZ/20011942/Ksd3

Kenneth

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s Ding Awo

of 10 s/m

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_


Sum Insured: \_\_\_\_\_ Excess: 100%

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$30,500

IDAC Accident Report: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 12 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: Smk 763U Yr Regn: 12, 11

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA

Make: Volvo S60 T4 c.c. 1596

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 151576 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: YV1FS485BC-2093096

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / SRim / STD A/Rim or

Tyre Size: F: \_\_\_\_\_ R: 235/40R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front R/Bal. 7 mm Rear R/Bal. 7 mm

L/Bal. 7 mm L/Bal. 7 mm

D.O.A. 29/10/20 D.O.I. 3/11/2020

Survey held at \_\_\_\_\_

Des. of Damages: Fr / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV - \$30,500.00

LTA - \$ 25,052.00

NETT = 5,448.00

SUBMIT TOTAL LOSS AS NOT ECONOMICAL FOR REPAIR

Date/Time, File Pass to?

05/11/2020

1) TYPIST

Date/Time, File Return to?

: Prell. Report

: Final Report

Days Of Repair: 12

Resurvey No. of Trip: -

Survey Fee:

Transportation:

\$ + RS. SI

Fuel

Others

TOTAL

Add Fee:  Site Insp (\$

Interview (\$

Tech Invs (\$

Weekend (\$

Report Format: TOTAL LOSS

Lump Sum / I.B.I: (\$

Ding Auto Pte Ltd  
Sin Ming Industrial Est. Sec C, Blk  
10, #01-20  
575645



Insurer Reference: SMK763U  
Repairer Reference: 037350  
Date calculated: 31/10/2020 4:31 PM

Full Report  
Registration: SMK763U  
Printed: 31/10/2020 4:31 PM

### Summary Information

#### Claim

Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	Ding Auto	Currency:	SGD
Claim Reference:	SMK763U	Date of Incident:	29/10/20
Estimated Repair Time:	14	Hire Car Start:	
Actual Repair Days:		Hire Car End:	

### Vehicle Details

#### Vehicle

Manufacturer:	VOLVO
McName:	S60 (Z)
Sub Model:	BASE MODEL
Model Sheet Number:	41 27 01
Registration:	SMK763U
VIN number:	
Odometer:	151576
<b>Model Specs</b>	
2.0 LTR 184 KW	FRONT DRIVE



*Not Authorized*  
*1/1 Imp &*  
*Resurvey After Paint*


### Vehicle Condition

#### Vehicle Status

Pre-Accident Damage:  
Date of Inspection:

#### Damage Areas

All   
Ur.



## Labour

Code	Description	Time Base 10 WU/h		Price = 42.00 SGD/h	
		WU	Price SGD	WU	Price SGD
35208-2	RENEW BOTH COMPLETE HEADLAMP UNITS	9.0	37.80		
82510-3	RENEW L/FRT WING INCLUDES: L/F WING AND REQUIRED ATTACHED PARTS R + R	3.0	12.60		
82510-3	RENEW R/FRT WING INCLUDES: R/F WING AND REQUIRED ATTACHED PARTS R + R	3.0	12.60		
86170-2	RENEW COMPLETE FRONT BUMPER (REMOVED) INCLUDES: RADIATOR GRILLE, COVERS AND REQUIRED ATTACHED PARTS R + R	15.0	63.00		
86103-2	R + R FRONT BUMPER CPL	8.0	33.60		
82116-2	R + R FRONT BONNET CABLE	2.0	8.40		
82430-3	RENEW BONNET INCLUDES: R + R BONNET, ATTACH PARTS ASSEMBLE AND IF NEC RENEW	4.0	16.80		
82114-2)	R + R L/BONNET SEAL	1.0	4.20		
82114-2)	R + R R/BONNET HINGE	1.0	4.20		
84Nar2-2	R + R WINDSCREEN INCLUDES: R + R INTERIOR MIRROR, A-PILLAR TRIMS, DRIP MOULDING AND WIPER ARMS	22.0	92.40		
82314-3	REAR PANEL AIR GUIDE REMOVE AND REFIT	2.0	8.40		
NO NUMBER	R + R FRONT LOCK CARRIER	4.0	16.80		
NO NUMBER	RENEW L/WHEELHOUSE PANEL (FRONT SECTION)	30.0	126.00		
NO NUMBER	RENEW R/WHEELHOUSE PANEL (FRONT SECTION)	30.0	126.00		
36338-2)	R + R WATER RESERVOIR	4.0	16.80		
84625-2	R + R RIGHT DOOR MIRROR HOUSING COVER	2.0	8.40		
88107-2	RENEW DASHBOARD	39.0	163.80		
88425-3	R + R DRIVER AIRBAG	2.0	8.40		
26010-2	DRAIN + REFILL COOLANT	4.0	16.80		
26104-2)	R + R RADIATOR	4.0	16.80		
87408-2)	R + R AIR CONDITIONING CONDENSER	4.0	16.80		
77077-3	L/FRT WHEEL BALANCE	1.0	4.20		
77223-3	R + R LEFT FRONT TYRE	2.0	8.40		
87003-2	DRAIN/REFILL AIR CONDITIONING	7.0	29.40		
35202-2	ADJUST HEADLAMPS	1.0	4.20		
	<b>Labour Cost</b>	<b>Hrs</b>	<b>WU</b>		
	<b>Panel / Mechanical Labour</b>	<b>20.40</b>	<b>204.0</b>		<b>856.80</b>
	<b>Total of Labour</b>				<b>856.80</b>

## Paint

Code	Description	SYSTEM AZT		Time Basis 10 WU/h	
		WU	Price SGD	WU	Price SGD
	BONNET NEW PART PAINTING	24.0			
	L/F WING NEW PART PAINTING	9.0			
	R/F WING NEW PART PAINTING	9.0			
	FRT LOCK CARRIER SURFACE PAINT	4.0			

Code	Description	WU	Price SGD
	FRONT BUMPER NEW PART PAINT K1R	12.0	
	FRT TOWING EYE COVER NEW PART PAINT K1R	3.0	

**Paint Material Per Part**

Code	Description	Price SGD
0471	BONNET NEW PART PAINTING	70.12
0741	L/F WING NEW PART PAINTING	12.49
0742	R/F WING NEW PART PAINTING	12.49
1017	FRT LOCK CARRIER SURFACE PAINT	2.82
0283	FRONT BUMPER NEW PART PAINT K1R	51.30
0303	FRT TOWING EYE COVER NEW PART PAINT K1R	0.35

**Labour Cost - Paint**

Factor	Hrs	WU	Price SGD
			42.00 SGD/h
Time Paint		61.0	
Preparation Main Work Metal	0.70	7.0	29.40
Preparation Comp. Work Plastic	0.30	3.0	12.60
<b>Total</b>	<b>10 WU/h</b>	<b>71.0</b>	<b>298.20</b>

**Material Cost - Paint**

	Price SGD
New Part Painting	95.10
New Part Painting - Plastic K1R	51.65
Surface-/Blend Paint	2.82
Material-constant Metal	18.10
Material-constant Plastic	9.00
<b>Total</b>	<b>176.67</b>

**Spare Parts**

Code	Description	Part Number	Part Source	prices as at 2001-01-01	Price SGD
7749	AIR GUIDE	32224876	Original	CMA	550.00 ✓
0471	BONNET	31468167	Original	Bj	980.00 ✓
0471	BONNET INSULATION	31477350	Original	CMA	120.00 ✓
0500	CABLE	32234714	Original	Tn	250.00 ✓
4465	CONDENSER	32252574	Original	Pu	450.00 ✓
7445	DRIVER AIRBAG	39825814	Original	Burn	950.00 ✓
7789	ELECTRIC FAN CPL	31657360	Original	Tn	600.00 ✓
6010	ENTERTAIN SYSTEM CU	36011649	Original	Na	950.00 ✓
0379	FR LWR BUMPER GRILLE	31688372	Original	Red	190.00 ✓
1026	FRONT AIR DEFLECTOR	31455483	Original	CMA	150.00 ✓
0283	FRONT BUMPER	39796231	Original	Bj	650.00 ✓
0380	FRONT GRILLE SEAL	32260538	Original	Tn	100.00 ✓
0257	FRONT NUMBER PLATE	KNPL3	Original	mit	30.00 ✓
0340	FRT BUMPER ABSORBER	31455737	Original	CMA	180.00 ✓
1001	FRT BUMPER SUPPORT	31463938	Original	Bj	450.00 ✓
1017	FRT LOCK CARRIER	32244775	Original	CMA	350.00 ✓
0258	FRT NO PLATE REINF	KNPL0	Original	vd	35.00 ✓

Code	Description	Part Number	Part Source	Price SGD
1413	FRT SCREEN MNTG KIT	31651607	Original	Me 80.00 ✓
0303	FRT TOWING EYE COVER	39793969	Original	miy 30.00 ✓
0410	GRILLE	32132212	Original	Bu 600.00 ✓
4331	INSTRUMENT PANEL	31467481	Original	Ta 1,200.00 ✓
8741	INTERCOOLER	31338306	Original	2,200.00 ?
0475	L/BONNET HINGE	32277085	Original	Dit 85.00 ✓
1033	L/F AIRBAG SENSOR	31476275	Original	Me 80.00 ✓
0749	L/F LWR WING BRACKET	31468231	Original	Dit 80.00 ✓
0377	L/FOG LAMP COVER	31455513	Original	Seu 150.00 X
7227	L/F TYRE	215/60 R 16 .. V	Original	Pur 600.00 ✓
7201	L/F WHEEL	31471309	Original	CM 500.00 ✓
0741	R/F WING	31468170	Original	Bu 350.00 ✓
0583	R/LED UNIT	31427776	Original	CM 800.00 ✓
1135	L/W-HOUSE SUPPORT	31463930	Original	CM 250.00 ✓
0561	RIGHT LEFT HEADLAMP ASSY	32273067	Original	CM 2,100.00 ✓
0349	LWR AIR GUIDE PANEL	32227198	Original	Bu 300.00 ✓
7776	LWR RADIATOR HOSE	32224779	Original	80.00 ?
1412	PRIMER	1161824		0.00
0476	R/BONNET HINGE	32277086	Original	Dit 85.00 ✓
1746	R/DOOR MIRROR HSG	39849801	Original	miy 60.00 ✓
1034	R/F AIRBAG SENSOR	31476275	Original	Me 80.00 ✓
0750	R/F LWR WING BRACKET	31468232	Original	Dit 80.00 ✓
0372	R/FOG LAMP COVER	31455514	Original	Seu 150.00 X
0742	R/F WING	31468171	Original	Bu 350.00 ✓
0584	R/LED UNIT	31427776	Original	800.00 ?
1136	R/W-HOUSE SUPPORT	31463931	Original	R 250.00 X
7760	RADIATOR	32224829	Original	480.00 ?
0562	RIGHT HEADLAMP ASSY	32314193	Original	Bu 2,100.00 ✓
7773	UPPER RADIATOR HOSE	32252070	Original	80.00 ?
1436	WASHER BOTTLE	30747577	Original	200.00 ?
1401	WINDSCREEN	31468106	Original	CM 700.00 ✓
1411	WINDSCREEN BOND KIT	31299177		Me 0.00 ✓

f: OEM Parts  
n: Non-OEM Parts  
u: Used parts

<b>Savings</b>	0.00
<b>Subtotal</b>	21,535.00
<b>Total</b>	21,535.00

## Final Calculation

	SGD	SGD
<b>Parts</b>	21,535.00	
<b>Total Parts</b>		<b>21,535.00</b>
<b>Labour Time Base 10 WU/h</b>		
Total 204.0 WU X 42.00 SGD/h	856.80	
<b>Total of Labour</b>		<b>856.80</b>
<b>Paint Work Time Base 10 WU/h</b>		
Labour Cost 71.0 WU X 42.00 SGD/h	298.20	
Material Cost	176.67	
<b>Total Paint Including Material</b>		<b>474.87</b>
<b>Repair Cost Excludes GST</b>		<b>22,866.67</b>
GST (+7.0%)		<b>1,600.67</b>
<b>Repair Cost Included GST</b>		<b>24,467.34</b>

Nar

### Comments

- \* - USER SUPPLIED DATA
- NN - NO MANUFACTURERS CODE EXISTS
- ) - WU PARTIAL INCL IN OTHER POSITIONS

### Assessment Note

No assessment notes entered.

vuf

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report 31/10/2020 14:58  
Date Of Accident 29/10/2020 13:15  
Exact Location Of Accident BALESTIER ROAD TOWARD THOMSON  
Country/State of Loss SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number SMK763U

**Insured/Policyholder**  
Name Of Registered Owner TOH WEE FONG  
NRIC No SXXXX806Z  
Email Address NOEMAIL  
Mobile Phone No (LOCAL) +65-98509084  
Alternative Phone No OFFICE-98509084

**Vehicle Particulars**  
Manufacturer VOLVO  
Model S60-1.6 T4 (A)  
Exact Purpose for which vehicle was being used at time of accident  
Are you claiming under your own insurance policy for repair to your vehicle? YES  
If No, Please state action to be taken  
Vehicle Category PRIVATE CAR

**Insurance Company**  
Name of Insurance Company CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.  
Type Of Coverage COMPREHENSIVE  
Fleet Policy NO  
Policy Number DMPCSNW00068042000  
Cover Note Number

**Driver**  
Name of Driver TOH WEE FONG  
NRIC No SXXXX806Z  
Date Of Birth 14/12/1986  
Occupation INDOOR  
Date Of Driving Pass 27/09/2011  
Driving Experience 9 YEARS AND 1 MONTH  
Gender MALE  
Mobile Number (LOCAL) +65-98509084  
Fax Number  
Contact Number OFFICE\_98509084

Address

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OTHER - .

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

**General Information of the Accident**

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR

Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 2

Was any body injured in the Accident? NO

 any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

**Details of Police Action**

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

**Circumstances of Accident**

REFER TO ATTACHED ACCIDENT STATEMENT AND SKETCH PAN

**Attachment(s)**

Are accident photos available for attachment? YES

 there any video captured by Car Camera? NO

Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

Name of Driver

NRIC/Passport Number

Contact Number

Address


Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

RUBBISH TRUCK  
COMMERCIAL VEHICLE




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 29<sup>th</sup> OCT. 20, around 1.12pm, I was traveling along balcony road toward Thompson road - There was a rubbish truck stationary at the roadside. I was unable to brake in time and collided to the rear of the rubbish truck.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

  
 Policyholder's Signature  
 Date & Time: 2.44pm 31 OCT 20

  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time: 2.44pm

  
 Reporting Centre Personnel's Signature  
 Name: Kenneth Dily  
 NRIC/FIN No.: \_\_\_\_\_

GIARMC SketchPlanForm\_V3

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 806Z

### Vehicle Details

Vehicle No.: SMK763U

Vehicle to be Exported: Yes

Intended Deregistration Date: 02 Nov 2020

Vehicle Make: VOLVO

Vehicle Model: S60 T4 1.6 AT ABS D/AB 2WD 4DR TC

Primary Colour: Blue

Manufacturing Year: 2011

Engine No.: B4164T1041313

Chassis No.: YV1F5485BC2093096

Maximum Power Output: 132.0 kW (177 bhp)

Open Market Value: \$35,116.00

Original Registration Date: 27 Dec 2011

First Registration Date: 27 Dec 2011

Transfer Count: 1

Actual ARF Paid: \$35,116.00

### Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 26 Dec 2021

PARF Rebate Amount: \$19,313.00

### Intended COE Rebate Details

COE Expiry Date: 26 Dec 2021

COE Category: A - Car (1600cc & below)

COE Period(Years): 10

QP Paid: \$50,001.00

COE Rebate Amount: \$5,739.00

Total Rebate Amount: \$25,052.00

The information contained herein is correct as at 31 Oct 2020

OK