



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL

Ref : CS/AGI20011962/Avd3q2

(BUDGET DIRECT INSURANCE)

190 CLEMENCEAU AVENUE #03-01

SINGAPORE SHOPPING CENTRESINGAPORE

239924

Date : 30-11-2020



Code : AGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMQ 79E	Veh. Inspected	GBD 5769M
Policy No.		Coverage (\$)	0.00
Claim No.	C10007810	Excess (\$)	0.00
Assign From	IVY RATILLA	Assign Date	03/11/2020

2. Vehicle Particulars & Condition

Make & Model	CITROEN DISPATCH	c.c	1997
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	VF7XURHHAEZ011595	Colour	WHITE
Odometer	171014	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16C	GOODYEAR	6 mm
L/H Front Tyre	205/55 R16C	GOODYEAR	6 mm
R/H Rear Tyre	205/55 R16C	GOODYEAR	6 mm
L/H Rear Tyre	205/55 R16C	GOODYEAR	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	30/10/2020	Inspection Date	03/11/2020
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------