

**MOTORWAY**

1094 Lower Delta Road Motorway Building Singapore 169205

Main +65.6468 2200 | Fax +65.6273 5535

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

MOTOR CLAIMS DEPARTMENT

3 ANSON ROAD, #16-00

SPRINGLEAF TOWER

SINGAPORE 079909

ESTIMATES

VEHICLE NO. : GBB333E

CHASSIS NO : WV2ZZZ7HZ6X027456

ENGINE NO : AXE060996

MAKE / MODEL : VOLKSWAGEN / T5-SHUTTLE

YEAR : 29 Sep 2026

DATE OF ACCIDENT : 16.10.2020 @ 1115HRS

YOUR INSURED VEHICLE NUMBER : SLT8381A

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

PARTS DIScription

	QTY	List Price	Total List Price
1 REAR BUMPER <i>repair</i>	1	\$ 950.00	\$ 950.00
2 REAR FENDER LH <i>repair</i>	1	\$ 2,650.00	\$ 2,650.00
		Sub Total	\$ 3,600.00
		Less 10%	\$ 360.00
		Total	\$ 3,240.00

SPECIAL NETT ITEM

1 REAR BUMPER CLIPS <i>X</i>	1	\$ 40.00	\$ 40.00
		TOTAL	\$ 40.00

LABOUR CHARGES

1 REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING PANEL BEAT, CUT / WELD, STRAIGHTEN CHASSIS WHERE NECESSARY AND REPLACE ABOVE PARTS.	\$ 1,000.00	<i>400</i>
2 PUTTY AND SPRAY PAINT ALL AFFECTED AREAS (INNER/OUTER)	\$ 1,200.00	<i>500</i>
3 TO APPLY ANTI RUST TREATMENT ON THE REPLACED AND REPAIRED PANELS <i>X</i>	\$ 180.00	
	TOTAL LABOUR	\$ 2,380.00
	TOTAL PARTS	\$ 3,280.00
	GST 7%	\$ 396.20
	GRAND TOTAL	\$ 6,056.20

Prepared By : -

ANNIE TEW

Motor Claims

TEL: 6571 9642 FAX: 6278 5535

EMAIL: ainee@motorway.com.sg

*Ramu**4p 900/1000**3 days**P/P**08/11/2020 @ 10/10**Resy after repair*

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	16/10/2020 15:49
Date Of Accident	16/10/2020 11:15
Exact Location Of Accident	PENANG LANE (INFRONT SG SHOPPING CENTER)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBB333E
Insured/Policyholder	
Name Of Registered Owner	DE BEAUTE BEAUTY & SLIMMING PTE LTD
Co Reg No	2XXXXX660W
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-67381133

Vehicle Particulars

Manufacturer	VOLKSWAGEN
Model	T5-SHUTTLE-2.5 D (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	SI02V03359/VCV/R12
Cover Note Number	

Driver

Name of Driver	LEO MING JIN
NRIC No	SXXXX565I
Date Of Birth	09/01/1955
Occupation	INDOOR
Date Of Driving Pass	04/07/1974
Driving Experience	46 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93928888
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	72 DIDO STREET SINGAPORE
Postcode	459498
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	PAID DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	RIVER VALLEY NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: BLK 4 DELTA AVENUE , POSTCODE: 161004 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-2789999 - FAX NO: 62786427
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE SEE ATTACHED SKETCH

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1:

Vehicle Registration Number	SLT8381A
Vehicle Make/Model/Colour	HONDA / VEZEL HYBRID 1.5X AUTO
Details Of Properties	
Vehicle Category	PRIVATE HIRE
Name of Driver	WONG YOW KEE
NRIC/Passport Number	SXXXX094H
Contact Number	
Address	
Postcode	
Insurance Company Name	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

[Signature]

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Leo Ming Jin
50081568 I
16 Oct 2020
2:15 pm



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Client's Name: Excess: Gen. Cond: Good / Fair / Poor / Bunt 201120K 5233276

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling along penang lane, on the left lane a vehicle (SLT 8381A) was parked on the double yellow line and pick up a passenger. I was on the right lane after, i pass by his vehicle suddenly feel an impact on my rear. I stop and check he was hit onto my rear left tyre and bumper. [SLT 8381A - got old damages on the front right bumper and it was a dent on his vehicle.]

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:
Lea Ming Jin 500815651
16 Oct 2020 2.15pm.



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



E/20201016/2078

1 of 3

POLICE REPORT (NP299)

Report No. E/20201016/2078

Police Station Of Origin
River Valley NPP
4 Delta Avenue #01-02 SINGAPORE 161004
Tel No: 1800-2789999

Date/Time Report Made 16/10/2020 20:53	Vide Report No.	Station Diary No. 62
Name Of Informant LEO MING JIN	Address 72 DIDO STREET SINGAPORE 459498	
ID Type / ID No. NRIC NO / S00815651	Contact No. Home/Office	Mobile 93928888
Nationality SINGAPORE CITIZEN	Email Address	
Occupation Van driver	Sex Male	Age 65
Institution/School Name	Date of Birth 09/01/1955	Race Chinese
Date/Time Of Incident 16/10/2020 11:15	Location Of Incident PENANG LANE SINGAPORE Penang Lane towards Orchard Rd after Singapore Shopping Centre	


Brief details.

On the 16/10/2020 at around 1115hrs, I was driving my company van (GBB333E). I exited the basement carpark of Singapore Shopping Centre. As there were vehicles parked at the left lane, I then proceeded to the right lane of Penang Rd towards the direction of Orchard Rd. There was a Grab Car (SLT8381A) parked stationary along the double yellow line on the left lane to pick up a passenger.

After picking up the passenger, the Grab Car dangerously turned his car to the right hitting the rear left

Signature Of Officer Recording The Report: E / Sgt 3 GERALD WONG HOONG TEIK	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 16/10/2020 20:53
Officer In-Charge Of Case: E / Tanglin Police Divisional Investigation Branch / Sr Staff Sgt MUHAMMAD FAREEZ BIN MAKMOR Contact No.: 63914842	Classification Of Case:

Authentication Stamp



POLICE REPORT Pg. 1



**SINGAPORE
POLICE FORCE**



E/20201016/2078

2 of 3

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. E/20201016/2078

fender of my company van. As there was a jam forming up, I moved my vehicle forward to clear the traffic jam.

The grab car driver only provided me with his vocational license however he refused to provide me with his contact number and insurance detail. The grab driver was also seen talking to his passenger on his version of the accident.

I wished to state there was only minor scratches at my company van however there was a huge dent on the front right bumper of the grab car which is not possible as I am travelling at around 5-8km/h and the collision was minor. Later on, the driver was seen to be talking to someone on the phone and he subsequently pulled out his car bumper causing more damage. He was also seen taking a pictures of it. I did not know the motives of him doing it and I had an in-car camera in my van.

I am lodging this report as a record to submit this to my company's insurance company for their follow up action.

Details of the Grab driver

Name: Wong Yow Kee

NRIC: S0031094H

Subjects Involved	
Victim	
Person Name	LEO MING JIN (Informant)
Signature Of Officer Recording The Report: E / Sgt 3 GERALD WONG HOONG TEIK	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 16/10/2020 20:53
Officer In-Charge Of Case: E / Tanglin Police Divisional Investigation Branch / Sr Staff Sgt MUHAMMAD FAREEZ BIN MAKMOR Contact No.: 63914842	Classification Of Case:
Authentication Stamp	

POLICE REPORT Pg. 1



**SINGAPORE
POLICE FORCE**




E/20201016/2078

3 of 3

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. E/20201016/2078



*The sketch of the accident & the
photos at the scene are attached*



Signature Of Officer Recording The Report:

E / Sgt 3 GERALD WONG HOONG TEIK

Signature Of Interpreter:
Not applicable

Officer In-Charge Of Case:
E / Tanglin Police Divisional Investigation Branch /
Sr Staff Sgt MUHAMMAD FAREEZ BIN MAKMOR
Contact No.: 63914842

Authentication Stamp

Signature Of Informant:

Date/Time:
16/10/2020 20:53

Classification Of Case:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	660W
Vehicle No.:	GBB333E
Vehicle to be Exported:	No
Intended Deregistration Date:	05 Nov 2020
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	T5-SHUTTLE
Primary Colour:	Blue
Secondary Colour:	Black
Manufacturing Year:	2006
Engine No.:	AXE060996
Chassis No.:	WV2ZZZ7HZ6X027456
Maximum Power Output:	-
Open Market Value:	\$49,561.00
Original Registration Date:	30 Sep 2006
First Registration Date:	30 Sep 2006
Transfer Count:	2
Actual ARF Paid:	\$2,479.00
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Expiry Date:	31 Aug 2021
COE Category:	E - Open Category
COE Period(Years):	5
PQP Paid:	\$23,127.00
COE Rebate Amount:	\$3,792.00
Total Rebate Amount:	\$3,792.00

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

The information contained herein is correct as at 05 Nov 2020

OK

Blue

