



PRE-REPAIR INSPECTION REPORT				
LONPAC INSURANCE BHD		Ref: CS3/LPC20012018/Eqf3e2		
300 BEACH ROAD		Date: 09-11-2020		
#17-04/07 THE CONCOURSESINGAPORE 199555		Code: LPC2		
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	XB 9299B	Veh. Inspected	SFN 4356C	
Policy No.		Coverage (\$)	0.00	
Claim No.	20/20/20/VC05/023842	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	03/11/2020	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ C200	c.c	1991	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	WDD2053422F489998	Colour	WHITE	
Odometer	56315 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/40 R18	CONTINENTAL	5 mm	
L/H Front Tyre	215/40 R18	CONTINENTAL	5 mm	
R/H Rear Tyre	215/40 R18	CONTINENTAL	5 mm	
L/H Rear Tyre	215/40 R18	CONTINENTAL	5 mm	
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.			
5. General Information				
Accident Date	30/10/2020	Inspect Date / Time	04/11/2020 (10:58 AM)	
Survey held at	SKM GARAGE & TRADING LLC 10 KAKI BUKIT ROAD 2 #03-22 FIRST EAST CENTRE SINGAPORE 417868			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

Report Ref No. CS3/LPC20012018/Eqf3e2

Inspected By



CHEN TSUE YEE

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.