

ASS. REC. BY:

REF: C72/

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02

days

Res.: Yes or No

Lum Sum:

1-B.1

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

GBH 6284

Yr Regn:

12, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

NIS

Cobster

c.c

2953

Colour

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

442515815

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JNISC 2F 247 0861029

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NII / S/Rlm / STD A/Rlm or

Tyre Size:

F:

195R15XP

R:

155R12X8(D)

BS / OUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

9

mm

L/Bal.

9

mm

L/Bal.

9

9

mm

D.O.A.

27/10/20

D.O.I.

10/11/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rm O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS. SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

Lai Huat (Meng Kee) Motor Pte Ltd
160 Sin Ming Drive, #04-01, #04-02 &
#07-03, Sin Ming Autocity
575722

Insurer Reference: TP-SJV 890M
Repairer Reference: 71671
Date calculated: 03/11/2020 3:42 PM

Full Report
Registration: GBH628Z
Printed: 03/11/2020 3:42 PM

Summary Information

Claim			
Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	Jenny Lim	Currency:	SGD
Claim Reference:	TP-SJV 890M	Date of Incident:	28/10/20
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle			
Manufacturer:	NISSAN		
Model:	CABSTAR		
Sub Model:	BASE MODEL		
Model Sheet Number:	71 94 01		
Registration:	GBH628Z		
VIN number:			
Odometer:	4366		
Model Specs			
FROM 01/2017	AIR CONDITIONING	FOG LAMPS	3.0 LTR 110KW
SINGLE CAB	TWO COAT METALLIC	PREPARE OFF VEHICLE	

Not Authorised
Repairing

2 days

Labour

		Time Base 10 WU/h	Price = 42.00 SGD/h	
Code	Description		WU	Price SGD
UA10A1)	R + R FRONT BUMPER		6.0	25.20
UA10A1)	RENEW FRONT BUMPER (REMOVED)		2.0	8.40
NO NUMBER	R + R TYPE BADGE		3.0	12.60
RE20A1)	R + R RIGHT HEADLAMP		5.0	21.00
	(FRONT GRILLE REMOVED)			
	INCLUDES: REQUIRED COVERS			
	REMOVE AND REFIT.			
	ADJUST HEADLAMPS.			
NO NUMBER	R + R FRONT VENTILATION GRILLE		2.0	8.40
NO NUMBER	R + R BADGE NISSAN		3.0	12.60
0900	FRONT PANEL REPAIR		20.0*	84.00
Labour Cost		Hrs	WU	
Panel / Mechanical Labour		4.10	41.0	172.20
Total of Labour				172.20

Paint

Paint Work		SYSTEM AZT	Time Basis 10 WU/h	
Code	Description - TWO COAT METALLIC		WU	Price SGD
	FRONT AIR GRILLE NEW PART PAINT K1R		5.0	
	FRONT PANEL REPAIR PAINTING <50%		16.0	

Paint Material Per Part

Code	Description	Price SGD
0410	FRONT AIR GRILLE NEW PART PAINT K1R	13.28
0900	FRONT PANEL REPAIR PAINTING <50%	25.52

Labour Cost - Paint

	Hrs	WU	Price SGD
Factor	42.00 SGD/h		
Time Paint		21.0	
Preparation Main Work Metal	2.50	25.0	105.00
Preparation Comp. Work Plastic	0.50	5.0	21.00
Total	10 WU/h	51.0	214.20

Material Cost - Paint

	Price SGD
New Part Painting - Plastic K1R	13.28
Repair Painting	25.52
Material-constant Metal Preparation	28.60
Material-constant Plastic	9.00
Total	76.40

Spare Parts

				prices as at 2015-06-01/01	
Code	Description	Part Number	Part Source		Price SGD
0431	BADGE	99081 MB40C	Original	Ne	28.00 ✓
0432	BADGE MODEL	65092 LC65B	Original	Ne	55.00 ✓
0410	FRONT AIR GRILLE	62320 LC60A	Original	Ne	275.00 ✓
0281	FRONT BUMPER	62022 LC10B	Original	Ne	495.00 ✓
0257	FRONT NUMBER PLATE	KNPL3	Original		0.00
0562	RIGHT HEADLAMP ASSY	26010 LC65A	Original	CM	285.00 ✓
f: OEM Parts	Savings				0.00
n: Non-OEM Parts	Subtotal				1,138.00
u: Used parts	Total				1,138.00

Extras

Code	Description	Price SGD
1000	FRONT NUMBER PLATE	35.00* 25.00
	Total Extras	35.00

Final Calculation

	SGD	SGD
Parts	1,138.00	
Total Parts		1,138.00
Labour Time Base 10 WU/h		
Total 41.0 WU X 42.00 SGD/h	172.20	
Total of Labour		172.20
Total Of Extras		35.00
Paint Work Time Base 10 WU/h		
Labour Cost 51.0 WU X 42.00 SGD/h	214.20	
Material Cost	76.40	
Total Paint Including Material		290.60
Repair Cost Excludes GST		1,635.80
GST (+7.0%)		114.51
Repair Cost Included GST		1,750.31

Comments

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	29/10/2020 09:37
Date Of Accident	27/10/2020 08:30
Exact Location Of Accident	BLK 458 HOUGANG AVENUE 10 CAR PARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBH628Z
Insured/Policyholder	
Name Of Registered Owner	LIM'S PROVISIONS
Co Reg No	4XXXX000J
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-63878503
Vehicle Particulars	
Manufacturer	NISSAN
Model	CABSTAR 3.0 5M/T ABS 2DR 2WD
Exact Purpose for which vehicle was being used at time of accident	COMPANY USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1800102406-02
Cover Note Number	
Driver	
Name of Driver	LIM SEOW HONG
NRIC No	SXXXX713F
Date Of Birth	03/06/1958
Occupation	INDOOR
Date Of Driving Pass	12/07/1978
Driving Experience	42 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98658968
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 458 HOUGANG AVENUE 10 #04-409
Postcode	530458
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJV890M
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	JACQUEN THAM PECK THENG
NRIC/Passport Number	SXXXX531E
Contact Number	98555248
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

BK 458 Hongay Ave 10



On 28/10/2020 about 10 am, my Corry
GBH 6287 parked stationary at BLK 458 Hoxford
par park lot, the front part of my Corry was
found damaged which was hit by the vehicle B
pls see the photo attached.

The accident was informed by the driver of vehicle B and the particular is as below

Driver =
HP = 98555248
Driving Licence =

Insurer = China Tai Peap.

A GBH 628 I

 B = STU 890 M