



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL		Ref : CS/AGI20012061/Atf3q2		
(BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924		Date : 26-11-2020		
Code : AGI				
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMD 1659T	Veh. Inspected	SKQ 2714R	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10007841	Excess (\$)	0.00	
Assign From	IVY RATILLA	Assign Date	04/11/2020	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN SYLPHY	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	MNTBBAB17Z0020703	Colour	WHITE	
Odometer	116554	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	TOURADOR	6 mm	
L/H Front Tyre	205/60 R16	TOURADOR	6 mm	
R/H Rear Tyre	205/60 R16	TOURADOR	6 mm	
L/H Rear Tyre	205/60 R16	TOURADOR	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	02/11/2020	Inspection Date	04/11/2020	
Survey held at	F1 GARAGE PTE LTD 8 KAKI BUKIT AVENUE 4 #03-33 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		