



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO20012110/R1Ksd3q2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERS SINGAPORE 048623

Date : 25-11-2020



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBF 4806K	Veh. Inspected	SKV 4883X
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD2003211/AGC	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	05/11/2020

2. Vehicle Particulars & Condition

Make & Model	KIA FORTE K3 1.6A SX S/R	c.c	1591
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	KNAFZ411MF5509913	Colour	RED
Odometer	86572	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/45 ZR17	NEXEN	6 mm
L/H Front Tyre	215/45 ZR17	NEXEN	6 mm
R/H Rear Tyre	215/45 ZR17	NEXEN	6 mm
L/H Rear Tyre	215/45 ZR17	NEXEN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	03/11/2020	Inspection Date	16/11/2020
Survey held at	MOVA AUTOMOTIVE PTE LTD 15 FAN YONG ROAD SINGAPORE 629792		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	-----------------------