

ASS. REC. BY:

REF:

AIG/20012126/K+

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

4-6 days

Res.: Yes or No

Lump Sum:

1-B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

GBH 6621C

Yr Regn:

08, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

Mer Vito 114 CDis 2143

Colour

M. Black

A/C: Insured / Std / NI / NA

Sp. Reading

96679

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WDF 44760323351834

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD / Rim or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Double Star

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

23/9/20

D.O.I.

5/11/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear n/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prel. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS, SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16

AIG BUILDING

SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000

FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 23/09/2020

ESTIMATE

NO : QUOT202010-000005(00)

DATE : 02/10/2020

POLICY NO : 999995580

VEH REG NO : GBH6621C

MAKE/MODEL : MERCEDES BENZ VITO 114 CDI

PANEL VAN LONG AT ABS 5DR

CHASSIS NO : WDF44760323351834

ENGINE NO : 65195034274310

REG. DATE : 2018

Estimate Repair Cost to Vehicle No : GBH6621C

Description	Quantity	Unit Price	Amount
		S\$	S\$
PARTS			
1 Tailgate	1	1,350.00	1,350.00 ✓
2 Tailgate centre logo	1	48.00	48.00 ✓
3 Tailgate 'VITO' emblem	1	52.00	52.00 ✓
4 Tailgate 'C&C' emblem	1	38.00	38.00 ✓
5 Tailgate '109 CDI' emblem	1	62.00	62.00 ✓
6 Taillamp assy - LH	1	550.00	550.00 ✓
7 Taillamp lower garnish - LH	1	98.00	98.00 ✓
8 Rear bumper	1	850.00	850.00 ✓
9 Rear bumper clips	15	5.50	82.50 ✓
10 Rear fender - LH	1	780.00	780.00 ✓
			3,910.50
		Add 10%	391.05
			4,301.55
SPECIAL NET			
11 Rear windscreen sealant	1	60.00	60.00 ?
12 Tailgate '6 pax' sticker	1	25.00	25.00 125m
13 Tailgate '70km/h' sticker	1	25.00	25.00 125m
14 Rear bumper sensor	1	380.00	380.00 X
			490.00
LABOUR			
15 To remove and refit rear windscreen glass.	1	150.00	150.00 120L
16 To remove and refit rear bumper sensor	1	100.00	100.00 50L X
17 To check and rectify wiring system	1	80.00	80.00 20L
18 To transfer damaged tailgate interior mechanism to new tailgate.	1	150.00	150.00 60L
19 To remove and refit LH fender interior garnishes and trimboard, to facilitates the repairs	1	180.00	180.00 80L
20 To panel beat and straighten rear floorboard panel, rear chassis frame, rear LH fender inner panel, to cut and weld LH fender, including replacement of parts and align where necessary, to refit and adjust the same.	1	1,500.00	1,500.00 ?
21 To putty and spray paint on affected areas	1	1,200.00	1,200.00 800L
			3,360.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/09/2020 00:23
Date Of Accident	23/09/2020 16:30
Exact Location Of Accident	LEVEL 2 NORTHLINK MULTI STOREY CARPARK.
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBH6621C
Insured/Policyholder	
Name Of Registered Owner	DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD.
Co Reg No	1XXXXX778Z
Email Address	BENNY.CHONG@DAIMLER.COM
Mobile Phone No	
Alternative Phone No	OFFICE-68498118

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	VITO 114 CDI PANEL VAN LONG AT ABS 5DR
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	999995580
Cover Note Number	

Driver

Name of Driver	SUBRAMANIYAN MANIKANDAN
NRIC No	GXXXXX787K
Date Of Birth	01/02/1993
Occupation	OUTDOOR
Date Of Driving Pass	27/11/2017
Driving Experience	2 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90606506
Fax Number	
Contact Number	
EMail Address	SMAMIKANDAN220@GMAIL.COM

Address NIL
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - HIRER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
 Weather Conditions NA
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

ON THE DATE AND TIME MENTIONED I HAD PARKED MY VEHICLE AT THE SAID LOCATION WHEN IT WAS HIT BY A MOVING VEHICLE B, I HAD ASKED THE PARTICULARS OF THE DRIVER OF VEHICLE B, BUT THE DRIVER DID NOT GIVE ME ANY PARTICULARS AND MOVED AWAY FROM THE ACCIDENT SCENE. THERE IS A SECURITY CAMERA IN THE BUILDING AND MY COMPANY

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number XD2328L
 Vehicle Make/Model/Colour MITSUBISHI / FV51JP4RDEA
 Details Of Properties NA
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver NA
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

SKETCH PLAN

A: G6H6621C
B: XD2328L

6:XD2328L

LEVEL 2, NORM/LINK MS/CP.

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO ATTACHED STATEMENT.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

VERIFY BY AJAX MARS (ARC)
REPORTING OFFICER
HASHIM BIN KAMARI

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

ACCIDENT STATEMENT (2000 characters)

ON THE DATE AND TIME MENTIONED I HAD PARKED MY VEHICLE AT THE SAID LOCATION WHEN IT WAS HIT BY A MOVING VEHICLE B, I HAD ASKED THE PARTICULARS OF THE DRIVER OF VEHICLE B, BUT THE DRIVER DID NOT GIVE ME ANY PARTICULARS AND MOVED AWAY FROM THE ACCIDENT SCENE. THERE IS A SECURITY CAMERA IN THE BUILDING AND MY COMPANY


Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
HASHIM BIN KAMARI

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

24 September 2020 at 6:46 PM

Date/Time:

25 September 2020 at 6:46 AM