

ASSIGNMENT

File No.	Date:	Veh No.	SHA 4128P	Yr Regn	24 NOV 2016
Reported Case		Type: M.Car / M.Cycle / BUS / Van / Lorry	(Taxi) Private Motor		
Vehicle No.		Truck / Trolley or			
Make		Make	HYUNDAI 140	CC	1685
Colour		Colour	BLUE	AC	Insured / Not Insured
Sp Reading		Sp Reading	N/A	TRDg	Insured / Not Insured
Engine		Engine			
Chassis		Chassis	KMHLB41UMHU096579		
Gen. Cond.	Good / Fair / Poor / (Burnt)	Gen. Cond.	Good / Fair / Poor / (Burnt)		
Steering	Harder / Jammed / Locked / (Burnt)	Steering	Harder / Jammed / Locked / (Burnt)		
Brake	Harder / Jammed / Locked / (Burnt)	Brake	Harder / Jammed / Locked / (Burnt)		
Wheels	W / S / Rim / STD AVRim or	Wheels	W / S / Rim / STD AVRim or		
Tyre Size	18	Tyre Size	205 / 60 R16		
	R		11		
BS / CUN / EX / NOVA / GY / PS / LZA / MC / CH / SU / BR / SU /		BS / CUN / EX / NOVA / GY / PS / LZA / MC / CH / SU / BR / SU /			
NOVO / YOKO or		NOVO / YOKO or			
Front		Front			
R/Rat	-	R/Rat	-		
U/Rat	-	U/Rat	-		
CCA	31/3/2020	CCA	6/4/2020		
Survey Hold at		Survey Hold at	TP POUND		
Dist. of Damages	Front / Rear / O/S / N/S / J/C / Rock/Up or	Dist. of Damages	Front / Rear / O/S / N/S / J/C / Rock/Up or		
Vehicle	IN / OUT	Vehicle	IN / OUT		
Part of Damages		Part of Damages			



Action/ Instruction

VEHICLE BURNT. UNECONOMICAL TO REPAIR. RECOMMEND TOTAL LOSS.

13/11/20 Submit Ext T/L-BV:\$59,196.84 LTA:\$38,485.00 NV:\$20,711.84

Days Of Repair	Days Of Repair	Resurvey No. of Trip	Resurvey No. of Trip
Profr. Report	Profr. Report	Sundry For	Sundry For
File of Report	File of Report	Transportation	Transportation
13/11/20-Typist	13/11/20-Typist	Add Fee	Add Fee
Report Format	Report Format	Sho Insp	Sho Insp
Cumulative	Cumulative	Highway	Highway
		Tech Insp	Tech Insp
		Weekend	Weekend