

Enquire Vehicle's Insurance Particulars (As At 11 Sep 2020 / 08:10:00)

Vehicle No.:

SLU5134L

Make Description/Model:

TOYOTA / PRIUS HYBRID 1.8 CVT

Insurance Company Name:

MSIG INSURANCE (SINGAPORE) PTE LTD

Business Transaction Reference No.:

20200911101412925118

Please retain the business transaction reference number for Enquire Vehicle Owner Details (if required).



Lai Ai Fong has successfully logged out.

Your last login date and time was 11 Sep 2020, 10:13:39.

To return to ONE.MOTORING, please click [here](#)

For security reasons, please **CLEAR YOUR CACHE** after each session.

Session Transaction History

S/No	Asset Type	Asset ID	Asset Owner ID	Transaction Type	Transaction
1	Vehicle	SLU5134L	-	18.19 Enquire Veh Owner Info (Others) by Law Firm	7.49

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 11/09/2020 09:05
Date Of Accident 11/09/2020 08:10
Exact Location Of Accident AONG CTE BEFORE ERP GANTRY
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SFN1811A

Insured/Policyholder

Name Of Registered Owner KEE HAI SEONG
NRIC No SXXXX157A
Email Address NOEMAIL
Mobile Phone No (LOCAL) +65-96681109
Alternative Phone No OTHERS-96681109

Vehicle Particulars

Manufacturer HONDA
Model HONDA / ACCORD 2.4L

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number 5072980472-05
Cover Note Number

Driver

Name of Driver KEE TANNY(JI TANNI)
NRIC No SXXXX609C
Date Of Birth 08/04/1983
Occupation INDOOR
Date Of Driving Pass 21/06/2004
Driving Experience 16 YEARS AND 2 MONTHS
Gender FEMALE
Mobile Number (LOCAL) +65-97250992
Fax Number
Contact Number
EMail Address KEETANNY@GMAIL.COM

Address	7 JALAN TARI PAYONG THE MORNING DEW
Postcode	799254
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
Vehicle	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : SAMANTHA KEE GENDER: : FEMALE
Passenger 2	NAME: : SHI YI HUI GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes,Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes,against whom?	

Circumstances of Accident

REFER ATTACHED;

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLU5134L
Vehicle Make/Model/Colour	TOYOTA / PRIUS HYBRID 1.8 CVT
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TAN SENG SAN
NRIC/Passport Number	SXXXX301H
Contact Number	
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SMN3468L
Vehicle Make/Model/Colour	HONDA / SHUTTLE HYBRID 1.5 AUTO
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

IDAC KAKI BUKIT (VAC)
23 Kaki Bukit Ave 4 #02-02
Singapore 415933
Tel: 67416697 Fax: 67492305
Email: vackb@vicom.com.sg

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 11 SEP 2020

Reporting Centre Personnel's Signature
Name: 11 SEP 2020
NRIC/FIN No.:

Accident Sketch Plan

SKETCH PLAN

CTE

CTE

SMN 3484L SLA 5134L SPN 1811A

Lane 1

ERP gantry

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along CTE towards City at about 8:08am. Right ~~at the~~ junction before the ERP gantry, the vehicle in front of mine did a sudden e-brake which I did as well. The vehicle behind my car, SMN 5134L then did the same. However, ~~that~~ it later collided into the back of my car. At the point of accident, road is dry and weather is clear.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

SAFMC SketchPlanForm_v3

Driver's Signature
(If driver is not the policyholder)
Date & Time: 11th SEPT 2020

IDAC KAKI BUKIT (VAC)
23 Kaki Bukit Ave 4 #02-02
Singapore 415933
Tel: 67416697 Fax: 67492305
Email: vackb@vicom.com.sg

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.: 11 SEP 2020

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Addendum Sheet



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
6 Raffles Quay #18-00 Singapore 048380
Tel (65) 6224 0010 Fax (65) 6224 0030
Operating Hours: Monday to Friday, 09:00 – 17:00
UEN: 566550020G / GST Reg. No.: M400017735

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : MVA320078544 Vehicle Registration No: SFN1811A

Name(as shown in NRIC) : KEE TANNY (JI TANNI) NRIC/FIN/Passport No : S8310609C

(*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate

Address : 7 JALANTARI PAYONG THE MORNING DEW Singapore(799254)

Contact (Tel) : - Mobile No.: 81885539

Email Address : -

Date of Accident : 11.09.2020 Time of Accident: 08:10

Place of Accident : AONG CTE BEFORE ERP GANTRY

Insurance Company: NTUC

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

UPDATE: TO update gender to female

FILE BY SITI

Policyholder / Driver's Signature
Date: 11.09.2020

IDAC KAKI BUKIT

Reporting Centre Personnel's Signature
Name: SITI
NRIC/FIN No.:
Date: 11-09-2020

PRO-OPTION SERVICES

Mailing address: Blk 1898 Rivervale Drive, #04-1004, Singapore 542189

Mobile: 9 0610543 Email: mirage1195@gmail.com

Report No. : 266M0920.HK
Vehicle no. : SFN1811A

INVOICE

Kee Hai Seong
c/o 1 Kaki Bukit Avenue 6
#02-37
Singapore 417883

Invoice no : POS 266/20
Date: 1 October 2020

Item	Description	Qty	Unit price (\$)	Total Amt (\$)
01	Being charges for the inspection of the accident vehicle, transport and photographs.			696.00
(SGD: Six Hundred and Ninety-six only		GRAND TOTAL:		696.00

**Cheque should be crossed and made payable to "Pro-Option Services"*

PRO-OPTION SERVICES



Authorized Signature

PRO-OPTION SERVICES

Mailing address: Blk 189B Rivervale Drive, #04-1004, Singapore 542189

Mobile: 9 0810543 Email: mirage1195@gmail.com

Report No. : 266M0920.HK
Vehicle No. : SFN1811A

ACCIDENT VEHICLE SURVEY REPORT

1 REFERENCE

Date of Inspection : 11 September 2020
Requested by : Kee Hai Seong
c/o 1 Kaki Bukit Avenue 6
#02-37
Singapore 417883
Type of Survey : Independent
Repairer : Hua Kian Motor Workshop
1 Kaki Bukit Avenue 6 #02-37 Autobay @ Kaki Bukit S(417883)
Date of Accident : 11 September 2020

2 VEHICLE DATA

Make/Model : **HONDA ACCORD 2.4L**
Year of registration : 29 Jul 2008
Chassis No. : MRHCP26308P020507
Engine No. : K24Z21957460
Engine Capacity : 2354 cc
Odometer Reading : 156236 km
Colour : Golden

3 STATIC CHECK

Steering	: Serviceable	Paintwork	: Good
Foot Brake	: Serviceable	General Condition	: Good
Hand Brake	: Serviceable		

4 TIRE CONDITION

	<u>RH/Make</u>	<u>LH/Make</u>	<u>Size</u>
Front Tread	: 5 mm/Yokohama	5 mm/Yokohama	185/70R14
Rear Tread	: 5 mm/Yokohama	5 mm/Yokohama	185/70R14

5 GENERAL DESCRIPTION OF DAMAGE

Rear bumper squashed/torn, rear end panel dented/bent/distorted, spare tyre panel crumpled/distorted, rear RH fender bent, rear boot lid hinges bent, etc. Please see para. 8 of this report for more details.

6 REMARK

This inspection is carried out on a "WITHOUT PREJUDICE" basis and we have not authorized any repairs.

7 RECOMMENDATION

Recommended cost of repairs = **\$6,400.00** (lump sum)
Estimated no. of days for repairs = **Eight (8)**

B DAMAGE AND REPAIR COSTS ASSESSMENTReport No. : 266M0920.HK

Vehicle No. : SFN1811A

<u>Description</u>	<u>Qty</u>	<u>Assessed Condition</u>	<u>Repairer's Estimate (\$)</u>	<u>Revised Amount (\$)</u>
A SPARE PARTS				
Rear bumper	1	squashed/torn	707.70	707.70
Rear bumper side retainer LH	1	broken	43.00	43.00
Rear bumper clip	10	necessary	55.00	55.00
Rear bumper reinforcement	1	bent/distorted	257.10	257.10
Rear end panel	1	dent/bent/distorted	422.40	422.40
Rear end panel garnish	1	squashed/bent	94.00	94.00
Rear end panel garnish clip	4	necessary	23.20	23.20
Spare tyre panel	1	crumpled/distorted	1,238.80	1,238.80
Spare tyre panel board	1	to reuse	232.00	0.00
Rear boot lid	1	bent/distorted	728.20	728.20
Rear boot lid lock assy	1	bent/distorted	189.20	189.20
Rear boot lid lower catch	1	to repair	19.40	0.00
Rear boot weatherstrip	1	to reuse	56.90	0.00
Rear boot lid hinge	2	to repair	102.40	0.00
Rear boot lid "Honda" logo	1	necessary	21.80	21.80
Rear boot lid "2.4 i-VTEC" emblem	1	necessary	50.20	50.20
Rear boot lid "ACCORD" emblem	1	necessary	24.00	24.00
RH taillamp assy	1	side bracket bent	283.50	283.50
RH taillamp lower bracket	1	bent/distorted	11.60	11.60
RH rear fender	1	to repair	908.90	0.00
Exhaust silencer	1	bent/torn	998.80	998.80
		Subtotal of the above	6,468.10	5,148.50
		Discount 20%	1,293.62	1,029.70
		Subtotal 1:	5,174.48	4,118.80
Rear parking sensors (set)	1	broken	280.00	280.00
Spare tyre panel sound proofing pad	1	necessary	200.00	200.00
End panel joint rubberised sealer	1	necessary	150.00	150.00
		Subtotal 2:	630.00	630.00
		Total cost of parts	5,804.48	4,748.80

B LABOUR

To check wiring condition and repair where needed.	45.00	30.00
To install rear parking sensors and check sensing functions.	80.00	60.00
To apply anti-rust undercoating.	200.00	120.00
To remove and replace exhaust silencer	120.00	90.00

Report No. : 266M0920.HK

Vehicle No. : SFN1811A

To remove and transfer rear boot lid wire harnesses, fittings and attachments to new boot lid.	120.00	90.00
Labour charges to remove and replace, to cut and weld, to knock and reshape affected parts/areas.	2,100.00	1,500.00
Spray painting charges to putty and spray all affected parts/areas – rear bumper, rear RH fender, rear end panel, spare tyre panel, rear boot lid , rear boot lid hinges, etc.	1,500.00	1,250.00
Total labour cost	4,165.00	3,140.00
TOTAL COST OF REPAIRS	9,969.48	7,888.80

9 CONCLUSION

The revised or adjusted cost of repairs to restore the vehicle is \$7,888.80

- (a) The recommended cost of repair based on lump sum repair basis would be \$6,400.00
- (b) The estimated number of days for the repairs would be Eight (8)
(1st Re-inspection conducted on 12 September 2020)
(Post Repair Inspection conducted on 18 September 2020)

The above recommendations in my view are fair and reasonable for the restoration of the vehicle to its pre-accident condition.

Note: Lump Sum Repair Basis

This means the repairer is allowed to replace the damaged parts with used, reconditioned or new parts, or repair it to a roadworthy condition.

Prepared by:


Liaw Leong San
Licensed Automotive Appraiser

Dated: 1 October 2020

HUA KIAN MOTOR WORKSHOP

Blk 1 Kaki Bukit Ave 6

Autobay #02-37

Singapore 417883

Tel: 6842 5949

Kee Hai Seong

C/o Hua Kian Motor Workshop
1 Kaki Bukit Ave 6
#02-37
Singapore 417883

01 October 2020

Dear Sir,

Date of accident : 11/09/2020

Final repair bill to SFN 1811 A

To Supply,

Jump sum repairs recommended By the surveyor	\$6,400.00
Total	\$6,400.00

Dollars : SIX THOUSAND AND FOUR HUNDRED ONLY

TAX INVOICE

GST REG. NO.: 200106276D

INVOICE TO:
KEE HAI SEONG 7 JALAN TARI PAYONG SINGAPORE 799254

DATE	INVOICE NO.
21-Sept-2020	A 42087

DESCRIPTION	NO. OF DAYS	RATE	AMOUNT
RENTAL FROM 11 SEPTEMBER 2020 TO 18 SEPTEMBER 2020	7	112.15	785.05
GST @ 7%			\$54.95
TOTAL			\$840.00

All cheques must be made payable to BKW Rent A Car Pte Ltd.
Please write the vehicle and invoice number on the reverse.

