Kaki Bukit Autohub, 2 Kaki Bukit Ave 2, #01-18

Singapore 417921

Tel No.: +65 6842 0051 / 6744 0510 Fax No.: +65 6741 0510

Company Reg. No.: 200616038C GST Registration No.: 200616038C

Our Ref:

SGG 8535 B

Your ref:

SJC 5816 X

05 November 2020

AUTO & GENERAL INSURANCE (S) PTE LTD

SINGAPORE SHOPPING CENTRE 190 CLEMENCEAU AVENUE #03-01 SINGAPORE 239924 Attn: Motor Claims Department

Dear Sir/Madam.

NAME OF CLAIMANT: 88 MOTOR TRADING

VEHICLE NUMBER: SGG 8535 B

YOUR INSURED VEHICLE NUMBER : SJC 5816 X ACCIDENT ON 31 Oct 2020 ALONG TAMPINES AVE 1

AT ABOUT 10:10 HOURS

We refer to your email/fax dated **05 Nov 2020** informing that you wish to conduct a pre-repair survey and your List of Surveyors.

Our client confirmed appointment **LKK Auto Consultant Pte Ltd of Adrian Ling** as the Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at:

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit Autohub 2 Kaki Bukit Avenue 2 #01-18

Singapore 417921

Contact Person:

6842 0051 / 6744 0510 (Melody)

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully,



(Name & Signature):

inspection. Thank you! Appointed surveyor :

FOR SURVEYOR:

Date & Time of Inspection:

Please initial here after completion of pre-repair

N-51 AUTOMOTIVE PTE LTD