

ASS. REC. BY:

REF: CS3/MSG20012162/R1qf3

Special Instruction:

Surveyor: RASUL

ASSIGNMENT (Office)

From (Person): CRYSTAL LEE of MSIG Date/Time: 6/11/2020 10:45 AM

Estimated Cost: Bill to:

OD ☒ TP WS/ TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLE 454E Insured: XD 2967S

at Workshop m/s Million Auto Service Tel: 62649091/82285020

of No.4 Penjuru Place #01-12

Policy No: 1001528763 Claim No: 249466

Sum Insured: Excess:

Make of Veh: D.O.A. 04-11-2020
(Client's Record)

CA / REV / REP. / REV 24 HRS

"WP"

H.O.D. Endorsement:

Date/Time: 06-11-20 10.51A.M Person Contacted: MS CHEONG Vehicle IN ☒ OUT

Date/Time	Action/Instruction (X) Estimate
	SLE 454E- X
	XD 2967S- CS3/MSG18015025/Gtd3e2-1 DOA :10/08/2018