

ASS. REC. BY:

REF:

EQ / 200121801KV

MATH

ASSIGNMENT

From:

Estimated Cost:

OD / P / WS / TP / RES / QD / RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

Veh No:

SHD 419K

Yr Regn:

12, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Renault Latitude

c.c

1995

Colour

M-White / Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

606888

T/Radio: Insured / Std / NI / NA

EngNo:

CNo:

VF1ABL15AUC

283417

Gen. Condi: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: M / S / Rim / STD A/Rim or

Type Size:

F: 215/60R16

R:

NIS	OS

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report

GIA / PR Seen: Consistent? : Yes or No

Consistent? : Yes or No

Est. Repairs: 02 days Res.: Yes or No

Res.: Yes or No

Sum Sum: 20 % 3 Val.: Yes or No

3 Val.: Yes or No

2A / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date / Time

Person Contacted:

Action / Instruction

The UIC / Chassis frame / Body Structure affected due to collision.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Roof top or

Front
R/Bal. 9 mm
L/Bal. 9 mm
D.O.A. 3/11/20
Survey held at

Rear
R/Bal. 8 mm
L/Bal. 8 mm
D.O.A. 4/11/2020

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Sailun

6/11/20 6/11/20 2550k Summit (Red 17,155.93, 87%)

/Time, File Pass to?

: Prelim. Report

/Time, File Return to?

: Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

S + FS, SI

F + FS

Others

Weekend (\$)

TOTAL

ort Format:

up Sum / L.B.I.: (\$)

Add Fee:

: Site Insp (\$)

: Interview (\$)

Tech Invs (\$)

Weekend (\$)