





PRE-REPAIR INSPECTION REPORT				
LONPAC INSURANCE BHD		Ref: CS3/LPC20012257/Eqf3e2		
300 BEACH ROAD		Date: 12-11-2020		
#17-04/07 THE CONCOURSESINGAPORE 199555		Code: LPC2		
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SGG 3158P	Veh. Inspected	SJN 716B	
Policy No.		Coverage (\$)	0.00	
Claim No.	19/20/20/VP05/023872	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	09/11/2020	
2. Vehicle Particulars & Condition				
Make & Model	HONDA FIT	c.c	1339	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	GE61150591	Colour	RED	
Odometer	186667 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/45 R16	MICHELIN	5 mm	
L/H Front Tyre	195/45 R16	MICHELIN	5 mm	
R/H Rear Tyre	195/45 R16	MICHELIN	5 mm	
L/H Rear Tyre	195/45 R16	MICHELIN	5 mm	
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.			
5. General Information				
Accident Date	03/11/2020	Inspect Date / Time	10/11/2020 ( 11:38 AM )	
Survey held at	Top 93 Pte Ltd-51 Ubi Ave 1,#01-05 Paya Ubi Indust			
Repairer	-			
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

Report Ref No. CS3/LPC20012257/Eqf3e2

Inspected By



CHEN TSUE YEE

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.  
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or  
relying on this Report, in whole or in part, does so at his or her own risk.