

ASS. REC. BY:

Steve

REF:

CS3/LAC 20012263/End3

ASSIGNMENT

From:

PRS

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

DAC Accident Report:

Consistent? : Yes or No

SIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Cum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

No G/LA repair

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

Pop. Form:

Lump Sum / L.E.B. /

Veh No:

SKB 8079E

Yr Regn:

2011

Type: ☒ M Car / ☐ M. Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make:

NISSAN Qashqai

c.c. 1997

Colour:

Blue

A/C:

Insured / Std / NI / N

Sp Reading:

148204

T/Radio:

Insured / Std / NI / N

Eng/No:

C/No:

SJNFBAJ1042109539

Gen. Cond: Good ☒ Fair / ☐ Poor / ☐ BurntSteering: In order / ☒ Jammed / ☐ Leaked / ☐ Burnt orBrake: In order / ☒ Jammed / ☐ Leaked / ☐ Burnt orModl: Nil / ☒ STD / ☐ Rim or

Tyre Size:

F:

215/60R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / ☒ M/C / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

7/11/20

D.O.A.

10/11/20

Survey held at

Jementah Motor

Des. of Damages: Frt / ☒ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Photos

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$