

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	AXA INSURANCE	PTE LTD		Ref:	CC4/ASM20012279/Qea3q2	
	8 SHENTON WAY AXA TOWERSING			Date:	15/12/2021	
	ATTN:LYNN			Code:	ASM	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	GBG 6056P	Veh. Inspected	d	PA 28B	
	Policy No.	P1986410	Coverage (\$)		0.00	
	Claim No.	S0M02WQ1	Excess (\$)		0.00	
	Assign From		Assign Date		09/11/2020	
2.	2. Vehicle Particulars & Condition					
	Make & Model	ISUZU LT434P	c.c		7790	
	Engine No.	HIDDEN	Year of Reg.		2017	
	Chassis No.	JALLT434PH7000023	Colour		MULTI COLOUR	
	Odometer	166865 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	295/80 R22.5	DUNLOP		6 mm	
	L/H Front Tyre	295/80 R22.5	DUNLOP		6 mm	
	R/H Rear Tyre	295/80 R22.5	DUNLOP		6 mm	
	L/H Rear Tyre	295/80 R22.5	DUNLOP		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	04/11/2020	Inspection Da	te	11/11/2020	
	Survey held at	AT AUTO CONSULTANT				
		113 TECK WHYE LANE #05-650 SINGAPORE 680113				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days					