

22/02/2002

CS3/MSG19017834/Qsd3-1

A.S.S. REC. B

SUN PIN

REF:

~~CS3/MSG19017834/Qsd3-1~~

Special Instruction:

Surveyor: ~~Mark Sun~~

Maximen

KENNY ONG

ASSIGNMENT (Office)

06/11/2020

From (Person):

~~Mark Sun~~

of

MSG

Date/Time:

~~9/10/19 9:56am~~

Estimated Cost:

Bill to:

OD-TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLP 9803P

Insured:

SMP 1391 B

at Workshop m/s

Benefit Auto

Tel:

93291373

of

11 Kaki Bukit Road 1 # 01-02 Eunus Technolink

Policy No:

29135271 ALM

Claim No:

607906

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

7/10/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

12:35pm @ 9/10/19

Person Contacted:

Dunmy

Vehicle IN/OUT

Date/Time

Action/Instruction

131malid ✓

SLP 9803P - NA / AIG 19001007/h-y

DVA: 15/1/2019

SMP 1391B - NBA / INC 19017714/y

DVA: 7/10/2019

Dismantle: 10/10/2019

After repair: 16/10/2019

SUBMIT L/S \$7,200.00/7 DAYS

(\$5,550.12/RED - 44%)