

<<

Service Request Details

Claim
SOM02WT4

Reference
None 

Loss Date
November 7, 2020

Report Date
Nov 9, 2020 12:30:00 PM

Request Date
November 9, 2020

Due Date
November 9, 2021

Vendor Name
LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss
Own Damage

Services
Fire
Own Damage Investigation

Actions

Next Step
Finish the work

Complete Work

More ▾

Vehicle Information

Incident Vehicle Registration #
SKZ9085D

Model
SONATA 2.0

Service Address

38, , , 757700

Primary Contact/Insured

TAN JIA YONG KENNETH
BLOCK 259C PUNGGOL FIELD, #06-47, 823259, Singapore
94775211
KENNETHON@GMAIL.COM

Claim Handler

TEO Kitty
6568804602
kitty.teo@axa.com.sg

Additional Instructions
Please conduct fire investigation

- Messages
- Invoices
- History
- Documents
- Assessment
- Metrics
- Notes

Document Type

Document SubType

▼

▼

+ Upload Documents

NAME	 Estimate - CYS.msg
TYPE	Forms / Claim Documents
SUB-TYPE	Estimate / Quotation
AUTHOR	TEO Kitty
DATE UPLOADED	November 9, 2020

NAME

 GA484811-Policy Schedule.pdf

AUTHOR NIKAM Santosh Pandurang

DATE UPLOADED November 9, 2020

NAME  [GA484811-Certificate of Insurance.pdf](#)

TYPE Forms / Claim Documents

SUB-TYPE Policy Schedule / Covernote / Certificate of insurance

AUTHOR NIKAM Santosh Pandurang

DATE UPLOADED November 9, 2020

NAME  [SKZ9085D INSD GIA.pdf](#)

TYPE Reports & Statement

SUB-TYPE GIA Report

AUTHOR NIKAM Santosh Pandurang

DATE UPLOADED November 9, 2020
