REF: CS4/ASM 20012296/P SIMILLIA ASSIGNMENT SKZ 90850 Yr Regn: 2006 1 Date: /////2020 Veh No: Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Estimated Cost: OD / TP / WS / TP RES / OD RES / EVA / INV / MV Truck / Trailer or To Inspect Vehicle No: SKZ 90850 Make: Hadim Sonuta NE c.c 1,998 at Workshop m/s CYS Hutonbbile. (woodlands) Colour T/Radio: Insured / Std / NI / NA Sp.Reading HILL KMHEU41BN64246863 Insured: Policy No. C/No: Claims No. SOMOZWT4 Gen. Cond: Good / Fair / Poor / Burnt Steering: Inorder / Jammed / Leaked / Burnt or Sum Insured: (Client's Record) Brake: Inorder / Jammed / Leaked / Burnty or Make of Veh: Modi: Nil / S/Rim / STD A/Rim or F: 215/60 116 (Policy Condition) Remark: The veh had commenced its O/S repair at the time of inspection. TOYO / YOKO or Bal. or Market Value: Front Consistent?: Yes or No R/Bal. IDAC Accident Rport: GIA / PR Seen: Consistent?: Yes or No Est. Repairs: Res.: Yes or No D.O.A. 7/11/2020 3 Val.: Yes or No Lum Sum: Des. of Damages : Ert Rear / O/S / N/S / U/C / Rooftop or CA / REV / REP. / 24 HRS Front engine totally burnt and danged Interior Vehicle: IN / OUT Person Contacted: The U/C / Chassis frame / Body Structure affected due to collision. Date / Time Action / Instruction PARF-\$3,097 NV - \$6K. NL - \$2,903 Date/Time, File Pass to? : Preli. Report Days Of Repair: : Final Report Resurvey No. of Trip: Survey Fee: Date/Time, File Return to? Transportation: Add Fee: Site Insp (\$) S+RS. SI Interview (\$) Photos Report Format: Tech. Invs (\$ Others \$170.00 SCDF Lump Sum / I.B.I: (\$ Weekend (\$

TOTAL