DATE : 02/11/2020 15:44:22 RERPORT-ID : TAC019R Page : 1 of 2 USER-ID : amoppr10 ACCIDENT REPORT District SE IP NUMBER Company SBS Accident 31/10/2020 ANDREW GOH E/4472/2020 Report No. Duty IO Date POH LEONG Accident 00:30 Shift Code PM SHIFT Report Date 02/11/2020 Time Place of Accident Aft slip rd from TPY Road Name Road Name Junction Final Cause Nature Of MINOR Accident Type TRAFFIC Accident DRY Road Surface Weather Code CLEAR Type Of STRAIGHT ROAD Operating Hours WORKED 9 HRS Location DUAL CARRIAGEWAY Traffic Flow Traffic Volume MODERATE Ambulance Traffic Control UNCONTROLLED Convey Type Of REAR BEING HIT Collision With VEHICLE Collision Serious Minor Injury 0 Fatal 0 Injury Police Photo Taken Y Police Report Report Ν Number Mechanical Bus Towed N Sketch Y Fault CFMS No Urgent CBR N CFMS Case N Status Damage To Bus SBS5050Z, rear portion damaged During incident period, I was driving off bus svc 231 along the Facts of Incident

During incident period, I was driving off bus svc 231 along the said rd when I heard a sound discovered that my bus rear portion being hit by a m/car (SKN1004D). As a result, my bus rear portion damaged while car front left damaged. Bus continued to off-svc back AMD after exchanged particulars.

Brief Particulars

Reason for Late Report

STATEMENT READ OVER TO ME

AND I AFFIRM IT TO BE TRUE AND CORRECT

CHANG SUPENG Admin Persannel Ang Mo Kio Depot

SIGNATURE OF STAFF

NAME AND DESIGNATION OF RECORDER

DATE : 02/11/2020 15:44:22 RERPORT-ID : TAC019R Page : 2 of 2 USER-ID : amoppr10 ACCIDENT REPORT

Buses Involved in the Accident

1 Bus No : SBS5050Z Bus Model : Scania KUB4X2(EEV), SD, AC, 2 Axle Bus Park : BRBP CCTV : Y

Driver Involved in the Accident

1 Driver Category: BC Driver No: 77836 Svc No: 231 Gender : MALE TPI Ng Beng Hin Svc RG : Name :

MALE Name: Ng Beng Hin Svc RG:
TPRG NRIC: \*\*383H Lic Class: SAP RG:

09/11/2015 Nationality: Singaporean Lic Exp Date: 31/12/2999 Date Join :

LSvc : 4.98 Age: 71

Address : Blk 536 Bedok North St 3 #12-886 **Postal Code:** 460536

Third Party Details

1 Name: CHINESE Vehicle No : SKM1004D Jiang Hua Race:

NRIC : \* \* Age : 0 Veh Color : Gender: Contact No: 91389171 Veh Type: Veh Damage : Front left damaged Veh Make :

Witness Details