

ASS. REC. BY:

Steve

REF:

CS3/CTI 20012311/E4J3

ASSIGNMENT

23 Mar 2016

From:

PRS

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

S116 6891 p

Yr Regn:

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Suzuki Swift

c.c 1372

Colour:

Black

A/C: Insured / Std / Nil / N

Sp. Reading

89288

T/Radio: Insured / Std / Nil / N

Eng/No:

C/No:

JSAFZC82500323852

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/55R16

R:

7

BS/ DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

5/4/20

D.O.A.

18/11/20

Survey held at

Benz Bodywork

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear RH

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

No GIA rpt

reper 10kg 1K - 2K
3 rep dys

submit prs report

Date/Time, File Pass to?

☐

: Prel. Report

()

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

3

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

\$ + RS \$

Photos

Others

TOTAL

Rep. Form:

Comp Sum / L.B. /