

ASS. REC. BY:

REF: CS/AGI20012318/Uqf3

Special Instruction:

Surveyor: MARCUSASSIGNMENT (Office)From (Person): IVY RATILLA of AGI Date/Time: 10/11/2020 2:15 PM

Estimated Cost: _____ Bill to: _____

OD: ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SJM 876C Insured: SMH 5870Bat Workshop m/s 1st Auto Pro Pte Ltd Tel: 9188 3197of 8 Kaki Bukit Avenue 4 Premier @ Kaki BukitPolicy No: _____ Claim No: C10007879/CH

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 05 NOV 2020
(Client's Record)

CA / REV / REP. / REV 24 HRS

"WP"

H.O.D. Endorsement: _____

Date/Time: 10-11-20 2.18P.M Person Contacted: CHRISTINA Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (☒) Estimate
	SJM 876C- NA/INC20012150/z4 DOA :05/11/2020
	SMH 5870B- NA/INC20012150/z4 DOA :05/11/2020