



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL

Ref : CS/AGI20012336/Avd3q2

(BUDGET DIRECT INSURANCE)
190 CLEMENCEAU AVENUE #03-01
SINGAPORE SHOPPING CENTRESINGAPORE
239924

Date : 25-11-2020



Code : AGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGD 9210Y	Veh. Inspected	SKV 6097K
Policy No.		Coverage (\$)	0.00
Claim No.	C10007919/KY	Excess (\$)	0.00
Assign From	IVY RATILLA	Assign Date	10/11/2020

2. Vehicle Particulars & Condition

Make & Model	AUDI A1	c.c	999
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	WAUZZZ8X8GB009768	Colour	BLACK
Odometer	96919	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/50 R16	BRIDGESTONE	6 mm
L/H Front Tyre	205/50 R16	BRIDGESTONE	6 mm
R/H Rear Tyre	205/50 R16	BRIDGESTONE	6 mm
L/H Rear Tyre	205/50 R16	BRIDGESTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	10/11/2020	Inspection Date	11/11/2020
Survey held at	AUTOMOBILE HUB ENTERPRISE 1 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	13 Working Days
--	------------------------