



Email : darren@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

CLEANING TECHNOLOGY MANAGEMENT PTE LTD
14 TAMPINES INDUSTRIAL DRIVE
SINGAPORE 528530

Attention : THE OWNER
Contact : 64819588

Estimate : ES007076

Date : 09/11/2020
Vehicle Num. : XD8401T
Make/Model : MAN TGM 18.280 4X2 BB-2013
Chassis/Eng# : WMAN08ZZ7DY296490/21834545853
Accident Date : 07/11/2020
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LABOUR :
TO SUPPLY VERDEGRO US-100K (TMA'S) TRUCK MOUNTED
ATTENUATORS (PASS NCHRP350 STS LEVER 3 C/W HYDRAULIC
LIFT UP
TO SUPPLY LABOUR FOR INSTALLATION

Labour Total S\$:

Dis
42k 59,800.00
1000 3,000.00

62,800.00

Total : 43k

part by part .
before / After paint photos .
One Q' up
11/11/2020
3 Days .

SingDollars : Sixty-Two Thousand Eight Hundred Only

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice Basis"
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total S\$:

62,800.00

COMPLETE VMS PTE LTD

This is only an estimate bases on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun