

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969

Our Ref : 3054-33165
Date : 11-11-2020
Time of Fax: _____

Via Fax : EMAIL
Your Insured: SV 7947 M
Date of Acc : 11-11-20

Attn: Motor Claims Department

ALC

Dear Sirs

SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO. SH D 4236 U

Our client has engaged us to repair the above vehicle and submit claims against the other party/parties-involved in the accident _

In accordance to the motor claims framework, we hereby request your presence at 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.

Enclosed, please find:

- i) Our initial estimate of repairs of the damaged vehicle;
- ii) Accident report made by our client.

I would appreciate it if you could call us to arrange for the survey of the vehicle:-

♦ Lim Kwok Eng	Tel: 6214 8316 or HP: 9824 0811	} jumanibm@cdge.com.sg Fax no. 6546 8156
♦ <u>Jumani Bin Masudin</u>	Tel: <u>6214 8315</u> or HP: <u>9635 5305</u>	
♦ Lim Tien Siong	Tel: 6214 8398 or HP: 9635 8546	
♦ Chiang Liat Choon	Tel: 6214 8314 or HP: 9296 6006	
♦ Larry Ng Nyuk Phin	Tel: 6214 8315 or HP: 9230 2824	
♦ Fauzy Bin Mokhtar	Tel: 6214 8319 or HP: 8125 9176	

→ If we do not hear from you within the next 48 hours, we shall deem that you have waived your rights to survey our client's vehicle and we shall proceed to engage independent surveyor without further reference to you. We henceforth reserve our rights to claim for Loss of Use and Loss of Rental during any delayed period of this survey arrangement.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

Thank you.

Yours faithfully

for Vice President
Crash Repairs & Claims Recovery

member of COMFORTDELGRO

Date/Time: 11.11.2020 14:02

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order:

JC NO.:305433169

CUSTOMER
AS COMFORT TRANSPORTATION PTE LTD
CUSTOMER NO. 7010045
ADDRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
(R) 65508755 (O)
(P)

REGN NO: SHD4236U

MILEAGE

MAKE: HYUNDAI

FUEL

E.....1/2.....F

MODEL IONIQ(G3)

DATE/TIME IN 11.11.2020 07:00

YR OF MANU. 25.10.2019

TARGET DATE

CHASSIS CODE KMHC851CVLU187347


COMPLETION DATE/TIME:

COUNT CARD NO.

JOB DESCRIPTION

Accident Date: 11.11.2020
NATURE: 3P 11.11.2020

3/NO LABOR CODE DESCRIPTION



BOOKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

No.: SHD4236U

JU AIG

Vehicle No.:

SHD4236U

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 11.11.2020

Time: 14:35:45

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305433169
 REGN NO : SHD4236U
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G3)
 DATE OF REGN : 25.10.2019
 DATE/TIME IN : 11.11.2020 07:00
 ACCIDENT DATE : 11.11.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0104-2256-G	IONIQVC PANEL ASSY-TAIL G	1	2,480.40	20.00	1,984.32
0002	04-01-0104-2270-G	IONIQVC EMBLEM-HYBRID	1	24.30	20.00	19.44
0003	04-01-0104-2271-G	IONIQVC EMBLEM-IONIQ	1	31.30	20.00	25.04
0004	28-01-0103-0005-A	REAR BOOT LOGO CTPL	1 N	30.00	2.00-	30.00
0005	28-01-0103-0006-A	REAR BOOT TEL NUMBER CTPL	1 N	30.00	0.20	30.00
0006	28-01-9999-2025-A	APP LOGO REAR BONNET CTPL	1 N	40.00	0.02-	40.00
0007	04-01-0104-2282-G	IONIQVC COVER-RR BUMPER#	1	459.40	20.00	367.52
0008	04-01-0104-2288-G	IONIQVC BEAM-RR BUMPER	1	394.80	20.00	315.84
0009	04-01-0104-2370-G	IONIQVC LAMP ASSY-REAR FO	1	201.50	20.00	161.20
0010	04-01-0104-2545-G	MOULDING-REAR BUMPER LWR	1	155.00	20.00	124.00
0011	04-01-0104-2540-G	COVER-RR BPR UNDER CTR	1	225.00	20.00	180.00
0012	04-01-0104-2546-G	COVER-RR BUMPER SIDE UNDE	1	108.00	20.00	86.40
0013	04-01-0104-2547-G	COVER-RR BUMPER SIDE UNDE	1	108.00	20.00	86.40

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 11.11.2020

Time: 14:35:45

Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305433169
 REGN NO : SHD4236U
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G3)
 DATE OF REGN : 25.10.2019
 DATE/TIME IN : 11.11.2020 07:0
 ACCIDENT DATE : 11.11.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0014 04-01-0104-2226-G	IONIQVC LAMP ASSY-LICENSE	1	85.30	20.00	68.24
0015 09-01-0104-2133-G	IONIQVC ANTENNA ASSY-SMAR	1	40.50	20.00	32.40
0016 09-01-9999-0068-A	HYUNDAI REVERSE SENSOR AS	1 N	180.00	2.00-	180.00
0017 04-01-0104-2533-G	MOULDING ASSY-RR BUMPER C	1	451.25	20.00	361.00
0018 04-01-0104-2380-G	IONIQVC LATCH ASSY-TAIL G	1	224.00	20.00	179.20
0019 04-01-0104-3819-G	IONIQVC STAY-RR BUMPER LH	1	138.10	20.00	110.48
0020 04-01-0104-3919-G	IONIQVC STAY-RR BUMPER RH	1	138.10	20.00	110.48
0021 02-01-0104-2099-G	IONIQVC MUFFLER ASSY-REAR	1	943.50	20.00	754.80
0022 09-01-0104-2184-G	IONIQV1-2 UNIT ASSY-BSD L	1	1,625.00	20.00	1,300.00
0023 09-01-0104-2185-G	IONIQV1-2 UNIT ASSY-BSD R	1	1,625.00	20.00	1,300.00
0024 04-01-0104-2346-G	IONIQVC PANEL ASSY-BACK	1	532.00	20.00	425.60
0025 FNPS	NO PLATE(S)	1 N	25.00	2.00-	25.00

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305433169
REGN NO : SHD4236U
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 25.10.2019
DATE/TIME IN : 11.11.2020 07:0
ACCIDENT DATE : 11.11.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

SUB-TOTAL : 8,297.36

JOB NATURE

0000 23-01	TOWING FEE	60.00	
0001 PB	PANEL BEATING	1000.00	
0002 SP	SPRAYPAINT CHARGE	700.00	
0003 17-01	CHECK ALL LIGHTING	50.00	
0004 20-00	TUFF COAT ON AFFECTED PARTS.	50.00	
0005 20-06	REMOVE/REFIX EXHAUST PIPE TO ASST REP	100.00	
0006 L	REMOVE/REFIX REVERSE SENSOR	80.00	
0007 L	REMOVE/REFIX REAR WINDSCREEN GLASS	120.00	
		SUB-TOTAL	: 2,160.00

COMFORTDELGRO ENGINEERING PTE LTD

Date: 11.11.2020

REPAIR ESTIMATE

Time: 14:35:45

Page: 4

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305433169
REGN NO : SHD4236U
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 25.10.2019
DATE/TIME IN : 11.11.2020 07:0
ACCIDENT DATE : 11.11.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 10,457.36

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :