

ASS. REC. BY:

REF:

CS/AH20012414/Ry 13

948H

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SGL8119Tat Workshop m/s DAIHA Auto Serviceof 1004, PAUL MERSTH LN 3 #01-27Insured: AH

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 79K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SGL8119T Yr Regn: 2017 / JANType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: B.M.W 216D SE Auto c.c. 1496Colour: GRY A/C: Insured / Std / NI / NASp. Reading: 99506 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBA 2E 320705B45287Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/60R16
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / NIC / OHTSU / PIR / SUMI /

TOYO / YOKO or WESTAKE

Front

R/Bal. 5 mmL/Bal. 5 mmD.O.A. 03/11/2020Survey held at DAIHADes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

R/Bal. 5 mmL/Bal. 5 mmD.O.I. 12/11/2020

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐ : Prell. ReportDays Of Repair: 3

1)

☐ : Final ReportResurvey No. of Trip: 1

Date/Time, File Return to?

2) 8/12/20-TypistAdd Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

\$ + RS. \$ _____

Photos

Others

TOTAL

Rep. Format: MerimenLump Sum / L.B.A. (\$ \$2002.75)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	948H

Vehicle No.:	SGL8119T
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Nov 2020
Vehicle Make:	B.M.W.
Vehicle Model:	216D SE AUTO
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	33909630B37C15A
Chassis No.:	WBA2E320705B45287
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$29,004.00
Original Registration Date:	24 Jan 2017
First Registration Date:	24 Jan 2017
Transfer Count:	0
Actual ARF Paid:	\$22,606.00

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Jan 2027
PARF Rebate Amount:	\$16,954.00

COE Expiry Date:	23 Jan 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,101.00
COE Rebate Amount:	\$31,030.00
Total Rebate Amount:	\$47,984.00

The information contained herein is correct as at 13 Nov 2020

OK

Silver



Merimen e-Claims



Used 2017 BMW 2 Series 216d A



mart.com/used_cars/info.php?ID=944225&DL=3736

▶ BMW 2 Series 216d Active Tourer

Overview

Financial

Accessories

Similar

Research

Photos

Map

Price

\$79,800

Fuel Type

Diesel (Euro 5 Engine and Above)

Depreciation ⓘ

\$11,270 /yr

View models with similar depre

Reg Date

06-Jan-2017

(6yrs 1mth 23days COE left)

Mileage

N.A.

Manufactured ⓘ

2016

Road Tax ⓘ

\$1,082 /yr

Transmission

Auto

Dereg Value ⓘ

\$46,538 as of today (change)

OMV ⓘ

\$27,843

COE ⓘ

\$50,101

ARF ⓘ

\$20,981

Engine Cap

1,496 cc

Power

85.0 kW (113 bhp)

Curb Weight ⓘ

1,395 kg

No. of Owners ⓘ

2

Type of Vehicle

Hatchback

Features

View specs of the BMW 2 Series Active Tourer Diesel (2015-2018)

Category

PARF Car

St

A

