Our Ref :	T 1120 / SHA3797P /KS(st)
Your Ref: Date :	19-Nov-2020
AIG ASIA PA	CIFIC INSURANCE PTE LTD



CDGE Taxi Claims Dept 59 Loyang Drive 4th Floor

Singapore 508969

ComfortDelGro Engineering Pte Ltd 205 Braddell Road Singapore 579701

> Mainline +65 6383 6280 Facsimilie +65 6280 9755

> > www.cdge.com.sq

Company Registration No: 199506048W

Workshops

Braddell 205 Braddell Road Singapore 579701

Loyang 59 Loyang Drive Singapore 508969

383 Sin Ming Drive Singapore 575717

Pandan 45 Pandan Road Singapore 609286

Ubi 320 Ubi Road 3 Singapore 408649

Sungei Kadut 7 Sungei Kadut Way Singapore 728791

4,507.75

78 Shenton Way

#07-16

WITHOUT PREJUDICE

Singapore 079120

Attn: Motor Claims Department

Dear Sir

ACCIDENT INVOLVING OUR TAXI SHA3797P YOUR INSURED SGH5454R ON 12-Nov-2020 AND OTHER

We are the authorised repair workshop for Comfort Transportation Pte Ltd, the owner of motor Vehicle No SHA3797P which was involved in the captioned accident with your insured vehicle. The vehicle owner and the taxi driver concerned have requested and authorized us to assist them in presenting their claims against the party responsible for all applicable matters arising from the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving : SGH5454R we are submitting these claim for your consideration on behalf of the claimants.

TAXI OWNER'S CLAIM

IAAI	OWNERSCEAM	Φ.	0.504.00
1	Cost of Repair	\$	3,531.00
2	5 days Loss of Rental @ \$ 114.95 per day	\$	574.75
3	Survey Report Fees (Surveyed by M/s LKK)	\$	-
4	GIA / LTA Search Fees	\$	2.00
5	GIA / Police Report Fees	\$	-
6	Towing Fee	\$	
		\$	4,107.75
HIRE	ER'S CLAIM		
7	5 days Loss of Income @ \$ 80.00 per days	\$	400.00

We enclose herewith the following documents to support the claims: -

Original repair bill: a)

LTA search slip/s of: b)

SGH5454R

GIA / Police report/s of: c)

SHA3797P

Letter of authority from owner / hirer / operator d)

) Photograph/s of Accident Scene

() Certificate of Insurance

) Witness statement/s () PIR (x) Downtime/Mileage record

Kindly look into the matter and let us hear from you on the settlement of the said claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the taxi driver.

Yours faithfully

Kazali Hj Selahudin

CDGE Taxi Claims Department

Tel: 6214 8736 Fax: 6214 1843 Email: kazali@cdge.com.sg

This is a computer generated letter. No signature is required.



LETTER OF AUTHORISATION

(NAF / PAF)

ACCIDENT INVOLVING i 40 SHA3797P , SGH5454R

ON 12-Nov-20 12:35

ALONG

SLIP ROAD FROM JALAN BUKIT MERAH TO HENDERSON ROAD

I / We

RAMZANI BIN OMAR

(Hirer) NRIC No.: SXXXX092H

and/or

(Relief) NRIC No.: SXXXX092H

Taxi Number

SHA3797P

hereby authorise ComfortDelGro Engineering Pte Ltd(CDGE):

- 1. To submit my/our claims for damages, costs and expense, including loss of earning (Pending successful recovery), loss of rental, medical fee and legal costs.
- 2. To have absolute discretion to agree to any settlement or compensation amount in respect of my/our claim against third party (except personal injuries and medical claims).
- 3. To sign Discharge Voucher on my/our behalf.
- 4. To accept any payment (claim proceeds) in respect of the claim against third party and payment by cheque shall be forward directly to CDGE in accordance with CDGE's instruction and made in favour of "ComfortDelGro Engineering Pte Ltd".

Date

12-Nov-2020

Name of Hirer

RAMZANI BIN OMAR

Hirer NRIC

SXXXX092H

Signature:

Address

325 TAMPINES ST 32 #02-404

520325

Contact No.

97830095



A member of COMFORTDELGRO

GST REG. NO. M2-8921817-3

TAX INVOICE

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701 Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops

Worksnops 59 Loyang Drive Singapore 508969 383 Sin Ming Drive Singapore 575717 45 Pandan Road Singapore 609286 320 Ubi Road 3 Singapore 408649

COMPANY REG. NO.: 199506048W

Page: 1

8010004

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY.AIG BUILDING #07-16 SINGAPORE 079120

SINGAPORE

CONTACT NO: 64193000

3225094

VEHCLE NO SHA3797P

NO/DATE 91533110 18.11.2020

MAKE HYUNDAI JOB NO. 305433386

MODEL I - 40

ODOMETER READING

DATE OF REG 17.03.2016

JOB TYPE

CHASSIS CODE KMHLB41UMGU085621

Description: 3P 12.11.2020

Invoice for Lump Sum Repair

Total Lump Sum Repair Amt 7.000

3,300.00 231.00

Total Invoice amount

3,531.00

Issued by : KATHERINETAN 18.11.2020 10:16:12 Repair Type : CLSO/57/57 Payment Type/Term : /Credit 30 days

ComfortDelGro Engineering Pte Ltd

A member of COMFORTDELGRO

Head Office: 205 Braddell Road Singapore 579701

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

ACCOUNT No.	INVOICE No.	AMOUNT	BANK/CHQ No.
	Y		

Our Ref:

CT20110193

Date: 18 November 2020



TO WHOM IT MAY CONCERN

Dear Sir/Madam

ACCIDENT ON

12/11/2020 @ 12:35 hrs

ALONG

SLIP ROAD FROM JALAN BUKIT MERAH TO

HENDERSON ROAD

INVOLVING

SGH5454R

We refer to the above-mentioned accident and wish to inform that Comfort Transportation Pte Ltd is the registered owner of the taxi bearing vehicle registration number SHA3797P (the "Taxi"). The Taxi was hired to RAMZANI BIN OMAR IC NO SXXXX092H a registered hirer-operator of Comfort Transportation Pte Ltd at the time of occurrence of the aforementioned accident at a rental rate \$114.95 per day (inclusive of GST).

Please be advised that the Taxi was insured with **MS First Capital Insurance Ltd** on a third party basis at the material time of the accident.

We wish to confirm that the aforesaid hirer-operator had obtained our permission to undertake repairs for damage on the Taxi arising from the said accident with a motor workshop of his choice.

Please liaise with the said hirer-operator or his authorized workshop directly for settlement of claims with third party's insurance company in respect of the said accident.

Yours faithfully

Philip Chia Manager, Fleet Safety

This is a computer generated letter. No signature is required.

DATE	NAME OF DRIVER	ONICABE BEADING	MILEAGE	HOURS OPERATED (TIME)	ATED (TIME)	L	NAME OF DRIVER
			(KM)	FROM	10	אַן	
2 = 8	(Note motor)	£ t t 6 8 5	705	0830	1930		e e
2	Right Sapie	589436	320	070 2230	27.30		
R / 11/9)	RAMBARI	589765	780	070	3330		
De / 11/ 16	1 Ster mt Di	590049	325	ofo	02/1		
(1111)	1 stemps	55098	105	1800	0000		
2/11/B)	5 7 4	5 90 3 69		ofo	1340		
14/11/2020	2 0 1	5,90494	SAM 3797	134E			
16/4/2020	I Kuine	Ledo Ledo	Rand	7	0 091		
7			0 st 10 1 4 5	5			
		7	T. E. S.	3			
7730 7729							
	A TABLE SERVICE AND ADDRESS OF THE PARTY OF		The state of the s				

. .



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE

6 Raffles Quay #18-00, Singapore 048580 Phone: +65 6224 0010 Fax: +65 6224 0030 Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

TAX INVOICE

Our Ref No:

GR-20-140185

Date of Request:

12/11/2020

Your Ref No:

Online Purchase

ComfortDelGro Engineering Pte Ltd 205 Braddell Road Singapore 579701

Dear Sir/Madam,

Enquiry Date

12/11/2020

Enquiry By

Catherine Por Moy Juan

⁻□ Vehicle No.

SGH5454R

Accident Date

12/11/2020

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

[X] GIRO [] Cash [] Cheque