# COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd 59 Loyang Drive Singapore 508969

Our Ref	•	3054331	C
	_		_

Via Fax

EMMEL

Date :

Time of Fax:

Your Insured:

Date of Acc: V2-W 20

Attn: Motor Claims Department

Aller

Dear Sirs

# SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO. SH

8876 Y

Our client has engaged us to repair the above vehicle and submit claims against the other party/parties-involved in the accident \_\_

In accordance to the motor claims framework, we hereby request your presence at 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.

Enclosed, please find:

- i) Our initial estimate of repairs of the damaged vehicle;
- ii) Accident report made by our client.

I would appreciate it if you could call us to arrange for the survey of the vehicle:-

<ul> <li>Lim Kwok Eng</li> </ul>	Tel: 6214 8316 or HP: 9824 0811
<ul> <li>Jumani Bin Masudin</li> </ul>	Tel: 6214 8315 or HP: 9635 5305j
<ul> <li>Lim Tien Siong</li> </ul>	Tel: 6214 8398 or HP: 9635 8546
<ul> <li>Chiang Liat Choon</li> </ul>	Tel: 6214 8314 or HP: 9296 6006
<ul> <li>Larry Ng Nyuk Phin</li> </ul>	Tel: 6214 8315 or HP: 9230 2824
◆ Fauzy Bin Mokhtar	Tel: 6214 8319 or HP: 8125 9176

jumanibm@cdge.com.sg Fax no. 6546 8156

If we do not hear from you within the next 48 hours, we shall deem that you have waived your rights to survey our client's vehicle and we shall proceed to engage independent surveyor without further reference to you. We henceforth reserve our rights to claim for Loss of Use and Loss of Rental during any delayed period of this survey arrangement.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

Thank you.

Yours faithfully

for Vice President Crash Repairs & Claims Recovery

# OMFORTDELGRO ENGINEERING

member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701 Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops
59 Loyang Drive Singapore 508969
383 Sin Ming Drive Singapore 609286
380 Sin Ming Drive Singapore 609286
Date/Time 320 wbtRoad 3 Singapore 708732

24 Senoko Loop Singapore 758156
7 Sungel Kadut Way Singapore 728791
501 Yiehun Industrial Park A Singapore 768732

Page : 1

eam:

ARC Repair TP(CLSO)1

JOB CARD Sales Order:

REGN NO: 8875Y

MAKE: HYUNDAI

MODEL IONIQ(G3)

YR OF MANU. 14.11.2019

CHASSIS CODE KMHC851CVLU188726

JC NO.: 305433199

E.....F

PATEGIME N 11.2020 10:10

COMPLETION DATE/TIME:

TARGET DATE

MILEAGE

**FUEL** 

OMER

18

COMFORT TRANSPORTATION PTE LTD

7010045

OMERNO 83 SIN MING DRIVE

Singapore SINGAPORE 575717

65508755

(R) (P)

DUNT CARD NO.


JOB DESCRIPTION

Accident Date: 12.11.2020

IATURE: 3P 12.11.2020

1/NO

LABOR CODE



KED & PASSED OUT BY:			
SERVICE AD	VISOR		CUSTOMER'S SIGNATURE
ledgement Slip		Exit Pass	
No.: SH 8875Y	JU AIG	Vehicle No.: SH 8875Y	
Service Advisor	Signature/Date	Name of Service Advisor	Date
urned tô Service Reception upon collection		To be kept by Security Guard	

#### COMFORTDELGRO ENGINEERING PTE LTD

Date: 12.11.2020

REPAIR ESTIMATE

Time: 11:54:04 Page: 1

COMPANY: THIRD PARTY'S CLAIMS (CAS)

**CUSTOMER:** 7010045

ADDRESS: COMFORT TRANSPORTATION PTE LTD

383 SIN MING DRIVE

**SINGAPORE SINGAPORE 575717** 

65508755

JOB NO

305433199

REGN NO

: SH 8875Y

MILEAGE

: 0000000000

MAKE

: HYUNDAI

MODEL

: IONIQ(G3)

DATE OF REGN DATE/TIME IN

: 14.11.2019 : 12.11.2020 10:10

ACCIDENT DATE 12.11.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2282-G IONIQVC COVER-RR BUMPER# 1 459.40 20.00 367.52

0002 04-01-0104-2533-G MOULDING ASSY-RR BUMPER C 1 451.25 20.00 361.00

0003 04-01-0101-0111-G HYUNDAI BUMPER COVER CLIP 10 L 22.00 20.00 17.60

0004 04-01-0104-1150-A IONIQVC PROTECTOR MAT 1 50.00 2.00- 50.00

0005 04-01-0104-2532-G BRACKET ASSY-RR BUMPER SI 1 55.80 20.00 44.64

SUB-TOTAL : 840.76

JOB NATURE

0000 PB

PANEL BEATING

400.00

0001 SP

SPRAYPAINT CHARGE

300.00

0002 L

REMOVE/REFIX REVERSE SENSOR

80.00

SUB-TOTAL : 780.00

#### COMFORTDELGRO ENGINEERING PTE LTD

**SURVEYOR NAME & SIGNATURE** 

Date: 12.11.2020 Time: 11:54:04

REPAIR ESTIMATE

Page: 2

COMPANY: THIRD PARTY'S CLAIMS (CAS)

**CUSTOMER: 7010045** 

ADDRESS: COMFORT TRANSPORTATION PTE LTD

383 SIN MING DRIVE

SINGAPORE SINGAPORE 575717

65508755

JOB NO

305433199

REGN NO MILEAGE

: SH 8875Y : 0000000000

MAKE

: HYUNDAI

MODEL DATE OF REGN : IONIQ(G3) : 14.11.2019

DATE/TIME IN

: 12.11.2020 10:1

ACCIDENT DATE

12.11.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 1,620.76

AUTHORISED: YES/NO

**MVA NAME & SIGNATURE** 

DATE:

DATE:

#### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3, Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

aforesaid.	
Control of the Control	ACCIDENT STATEMENT
Date Of Report	12/11/2020 10:59
Date Of Accident	12/11/2020 09:30
Exact Location Of Accident	31A PUNGGOL TWENTY-FOURTH AVE
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SH8875Y
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	1XXXXX821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG

Mobile Phone No

Alternative Phone No OFFICE-65508768

**Vehicle Particulars** 

Manufacturer HYUNDAI Model IONIQ

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category

TAXI

**Insurance Company** 

Name of Insurance Company INDIA INTERNATIONAL INSURANCE PTE LTD

Type Of Coverage THIRD PARTY FIRE AND/OR THEFT

Fleet Policy YES

Policy Number MCOM0015

Cover Note Number

Driver

Name of Driver TAN BOO HOE
NRIC No SXXXX453B
Date Of Birth 15/06/1961
Occupation OUTDOOR
Date Of Driving Pass 16/07/1979

Driving Experience 41 YEARS AND 3 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-90122781

Fax Number Contact Number

EMail Address 1652TANBOOHOE@GMAIL.COM

Address

BLK 505 ANG MO KIO AVENUE 8 #10-2694

Postcode

560505

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OTHER - TAXI DRIVER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

**General Information of the Accident** 

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

**CLEAR** 

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle)

2

involved in the accident Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

NO

ambulance?

Was any other material or property damaged?

YES

I have been approached by unknown person(s)

NO

soliciting/offering accident claims assistance. Number of Passengers (Including Driver)

3

NAME:

1 -

Passenger 1

GENDER:

**FEMALE** 

Passenger 2

NAME:

GENDER:

: MALE

**Details of Police Action** 

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

**Circumstances of Accident** 

PLS REFER TO ATTACHED / Type Of Accident: 3P REVERSE (REAR RIGHT TO LEFT REAR)

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

Was there any audio recorded?

NO

**DETAILS OF OTHER VEHICLE PROPERTY 1** 

Vehicle Registration Number

SCW3K

Vehicle Make/Model/Colour

**Details Of Properties** 

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Page 2 of 17

Postcode Insurance Company Name Nature Of Damage No. Of Passenger (Including Driver)

AIG ASIA PACIFIC INSURANCE PTE. LTD.: REAR RIGHT

# IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material
  facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information setout in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which my be sited outlisde of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared/disclosed:
  - to all insurers and/or any other third parties that assist in evaluating, investigation, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or ourt orders.

COMFORT TRANSPORTATION PTE LTD CO. REG. NO. 199303821R

Policyholder's Signature Date & Time: Driver's Signature (If driver is not the policyholder) Date & Time:

Reporting Centre Personnel's Signature

NRIC/Fin Notice Werey

R= SH887CY
B= SCW3K
CHOYCTA)
DESCRIBE CIRCUMSTANCES OF THE ACCIDENT  On the 12 11 12000 (P) 0930me, was driving
my 2 proservers at 310 and 33 olue to
There's a refricte part at the entrance of 33
my passeburger to pay for the Drax, Fare, Soldenly Thore's a feet on my tax, left rear partial
1 Olep out to anoth and familiant a remote of sowak was reversing out and hit onto my taxi.
Mo myrry of the point of accident.

### **DECLARATION**

We declare the foregoing particulars are true in every respect.

COMPORT TRANSPORTATION PTE LTU CO. REG. NO. 199303821R

Policyholder's Signature Date & Time:

Driver's Signature (if driver is not the policyholder) Date & Time:

Reporting Centre Personnel's Signature

NRIC/Fin No.: Olivie Wendy

12 NOV 2020









