

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

MIG C/P/P)
Date: 12.11.2020
Time: 11:54:04
Page: 1
JM

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305433199
REGN NO : SH 8875Y
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 14.11.2019
DATE/TIME IN : 12.11.2020 10:10
ACCIDENT DATE : 12.11.2020

JOB / PARTS DESCRIPTION QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2282-G	IONIQVC COVER-RR BUMPER#	1	459.40	20.00	367.52	/	DD	
0002 04-01-0104-2533-G	MOULDING ASSY-RR BUMPER C	1	451.25	20.00	361.00	X	NM	
0003 04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10 L	22.00	20.00	17.60	/	PK	
0004 04-01-0104-1150-A	IONIQVC PROTECTOR MAT	1	50.00	2.00-	50.00	X	NM	
0005 04-01-0104-2532-G	BRACKET ASSY-RR BUMPER SI	1	55.80	20.00	44.64	?	X NM	385-12
SUB-TOTAL :								840.76

JOB NATURE

0000 PB	PANEL BEATING	400.00	820	
0001 SP	SPRAYPAINT CHARGE	300.00	200	
0002 L	REMOVE/REFIX REVERSE SENSOR	80.00	30	550
SUB-TOTAL :				780.00

Star (LKK) nm PL
12/11/20, 2-30pc
2 d/s
P/P
My Bel Sky

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: