

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SJXP994J
at Workshop m/s choo moto-
of SHIB 6231E
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: 18k.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs: 6

days

Res.: Yes or No

Lum Sum: 20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: SJXP994J Yr Regn: 2 / 08
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or CA
Make: Toyota wish c.c 1794
Colour: Shu A/C: Insured / Std / NI / NA
Sp.Reading: 19338 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: 2NE10 037811
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or
Brake: Inorder / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

225/40ZR18
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Kapser

Front

Rear

R/Bal. 6

mm

R/Bal. 6

mm

L/Bal. 6

mm

L/Bal. 6

mm

D.O.A. 11/11/20

D.O.I. 13/11/20

Survey held at _____

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rear 2
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

100 units (27-2-2023)
LTA @ 11590 nett 6410

24/11/20 1/5 @ 5400 confirmed with Alu.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

)

)

446 Cecilia

CHOO MOTOR SPRAY PAINTER
1 KAKI BUKIT AVE 6 #01-39 AUTOBAY
SPORE 417883

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Not Authorized
13/11/20
2/5400/6 days

VEHICLE No :SJX 8994J

1PC	REAR DOOR N/S	Body DD	\$1,499.10	1245.10
1PC	REAR DOOR OUTER HANDLE N/S	11	\$299.20	X
1PC	REAR DOOR INNER LOCK N/S	Damaged/should	\$439.10	
1PC	REAR DOOR GLASS OUTER MOULDING N/S	ner	\$122.30	
1PC	REAR DOOR GLASS REGULATOR N/S	ner	\$325.10	X
1PC	REAR DOOR GLASS REGULATOR MOTOR N/S	ner	\$480.00	395.50
1PC	REAR DOOR INNER BRACKET N/S	ner	\$101.00	65.00
1PC	REAR DOOR INNER RUBBER N/S	11	\$233.20	X
1PC	REAR DOOR INNER TRIM BOARD N/S	De/Torn	\$855.10	645.10
1SET	REAR DOOR INNER TRIM BOARD CLIPS N/S	ner	\$50.00	
1PC	REAR FENDER N/S	Body DD	\$1,650.10	961.10
1PC	REAR FENDER GLASS N/S	11	\$680.00	X
1PC	REAR SHOCK ABSORBER N/S	800	\$399.20	X
1PC	REAR WHEEL HUB BEARING N/S	Damaged	\$485.00	
1PC	REAR AXLE BEAM	11	\$1,425.10	X
1PC	REAR BUMPER	DD	\$885.10	561.10
1PC	REAR BUMPER SIDE RETAINER N/S	ner	\$66.50	
1SET	REAR BUMPER CLIPS	ner	\$50.00	
1PC	TAILLAMP N/S	11	\$399.20	X
			\$10,444.30	

S.NETT

1PC	REAR SPORT RIM N/S	ner	\$800.00	500
1PC	REAR TYRE N/S	ner	\$200.00	60% 120
1PC	REAR DOOR FRAME VISOR N/S	ner	\$100.00	60
1PC	REAR DOOR OUTER STRIP N/S	ner	\$100.00	80
1PC	REAR FENDER GLASS SEALANT N/S	ner	\$50.00	40

TO CHECK WIRING	\$50.00	20
TO DISMANTLE & REFIX REAR REVERSE SENSOR	\$80.00	50
TO DISMANTLE & REFIX CHSHION UPHOLSTERY	\$120.00	80
TO DISMANTLE & REFIX REAR FENDER GLASS N/S	\$150.00	100
TO DISMANTLE & REFIX FUEL TANK	\$100.00	60
TO DISMANTLE & REAR UNDER CARRIAGE	\$280.00	120
TO TRANSFER REAR DOOR MECHANISM	\$100.00	60
TO SPRAY RUST PROOFING	\$100.00	60
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$1,500.00	700
TO PUTTY & SPRAY PAINTING	\$1,500.00	900
TOTAL	\$15,674.30	

2-5075.90

252
3806.92

54015 6758.92

COMPUTERISED 4 WHEEL ALIGNMENT HUNTER DSP700

Company: FASTECH AUTO PTE LTD
VIN: SJX 8994 J
Date: 12.11.20 15:03



SJX 8994 J

Factory Japan 2019.0.1 : Toyota : Wish : E10 Series : ANE10G

Front : Left

Actual	Before	Specified Range
-0°56'	-0°56'	-1°15' 0°15'
2°48'	2°48'	2°20' 3°50'
0°00'	-0°01'	-0°05' 0°05'
9°15'	9°15'	10°35' 12°05'
8°20'	8°20'	9°20' 12°20'

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-0°58'	-0°58'	-1°15' 0°15'
3°33'	3°33'	2°20' 3°50'
-0°03'	-0°04'	-0°05' 0°05'
7°52'	7°52'	10°35' 12°05'
6°54'	6°54'	9°20' 12°20'

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
0°02'	0°02'	-0°45' 0°45'
-0°45'	-0°45'	-0°45' 0°45'
1°24'	1°24'	
-0°04'	-0°04'	-0°11' 0°11'

Rear : Left

Actual	Before	Specified Range
-2°26'	-2°26'	-2°00' -1°00'
-0°29'	-0°29'	-0°02' 0°12'

Camber
Toe

Rear : Right

Actual	Before	Specified Range
-1°09'	-1°09'	-2°00' -1°00'
0°10'	0°10'	-0°02' 0°12'

Rear

Cross Camber
Total Toe
Thrust Angle
Axle Offset

Actual	Before	Specified Range
-1°16'	-1°16'	-0°30' 0°30'
-0°19'	-0°19'	-0°03' 0°25'
-0°19'	-0°19'	
0mm	0mm	