

ASS. REC. BY:

Steve

REF:

CS/CT120012500/Es f3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Cum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

GBK 5973C

Yr Regn:

1/7/19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Dyna 150

c.c 2982

Colour:

Silver

A/C: Insured / Std / Nil / N

Sp. Reading

33967

T/R Adlo: Insured / Std / Nil / N

Eng/No:

C/No:

JTFAT35Y10K 213594

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / S/D A/Rlm or

Tyre Size:

F:

195R15C

R:

1'

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

12/11/20

D.O.I.

13/11/20

Survey held at

1st Auto Pro

Des. of Damages (Fr) / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

MIV-65K

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (%)

☐

: Weekend (%)

Pop. Formed:

Lump Sum / L.B. 100



1st Auto Pro Pte Ltd

We Believe in Service

8 KAKI BUKIT AVENUE 4 PREMIER @ KAKI BUKIT #01-49 & #01-51/52 SINGAPORE 415875

Tel : 9188 3197 / 8614 6767 | Email: christina@1ap.com.sg

ESTIMATION QUOTE

CHINA TAIPING INSURANCE (SG) PTE LTD
3 ANSON ROAD #15-00
SPRINGLEAF TOWER
SINGAPORE 79909
ATTN: MOTOR CLAIMS DEPARTMENT

VEHICLE NO : GBK5973C
MAKE MODEL : TOYOTA DYNA
REFERENCE : 1AP-202011-12
DOA : 10-Nov-20
CLAIM TYPE : TP CLAIM

PAGE 1 OF 2

LIST ITEMS	QTY	LIST PRICE (\$)	REMARKS
FRONT PANEL / DD	1	\$ 1,200.50	
FRONT PANEL EMBLEM - DYNA / NPC	1	\$ 155.00	
FRONT PANEL WITH WIPER ATTACHMENT 2 / DD	1	\$ 575.00	
FRONT GRILLE WITH LOGO ?	1	\$ 610.00	
FRONT GRILLE TOP SEAL X	1	\$ 135.00	
FRONT WIPER GARNISH LH / RH X	2	\$ 516.00	
HEADLAMP LH / RH (RH) ?	2/1	\$ 2,900.00	
HEADLAMP RUBBER LH / RH X	2	\$ 290.00	
FRONT WING MIRROR - SQUARE X	1	\$ 305.00	
FRONT WING MIRROR - CIRCLE X	1	\$ 298.00	
FRONT WING MIRROR HOLDER X	1	\$ 188.00	
FRONT BUMPER / DD	1	\$ 899.80	
FRONT BUMPER REINFORCEMENT X	1	\$ 698.00	
FRONT BUMPER FOGLAMP LH / RH X	2	\$ 936.80	
FRONT BUMPER FOGLAMP COVER LH / RH X	2	\$ 443.20	
FRONT CORNER PANEL LH / RH X	2	\$ 770.00	
FRONT CROSSMEMBER X	1	\$ 985.80	
BRAKE PUMP SWITCH X	1	\$ 298.80	
BRAKE PUMP AIR BOX X	1	\$ 399.80	
RADIATOR SPARE TANK X	1	\$ 285.00	
AIR CLEARER BOX X	1	\$ 855.80	

\$ 13,745.50

LESS 25% \$ 3,436.38

SUBTOTAL \$ 10,309.13

BALANCE C/F \$ 10,309.13

SPECIAL NETT ITEMS	QTY	LIST PRICE (\$)	REMARKS
BALANCE B/F		\$ 10,309.13	
FRONT NUMBER PLATE / DR	1	\$ 100.00	40
FRONT BUMPER CLIPS / NPC	1	\$ 50.00	30
HEADLAMP CLIPS X	1	\$ 50.00	
FRONT WINDSCREEN SEALANT X	1	\$ 80.00	

SUBTOTAL \$ 280.00

BALANCE C/F \$ 10,589.13

ESTIMATION QUOTE

CHINA TAIPING INSURANCE (SG) PTE LTD
3 ANSON ROAD #15-00
SPRINGLEAF TOWER
SINGAPORE 79909
ATTN: MOTOR CLAIMS DEPARTMENT

VEHICLE NO : GBK5973C
MAKE MODEL : TOYOTA DYNA
REFERENCE : 1AP-202011-12
DOA : 10-Nov-20
CLAIM TYPE : TP CLAIM

PAGE 2 OF 2

LABOUR	S/NO	LIST PRICE (\$)	REMARKS
BALANCE B/F		\$ 10,589.13	
CHECK WIRING AND LIGHTING SYSTEM	1	\$ 100.00	30
PANEL BEATING ON AFFECTED AREA	2	\$ 2,000.00	600
SPRAY PAINTING	3	\$ 1,500.00	600
APPLY ANTI RUST ON AFFECTED AREA	4	\$ 150.00	30
SUBTOTAL		\$ 3,750.00	

GRAND TOTAL \$ 14,339.13

Steve CLKK) wL PL
13/11/20, 4-00p
5 dyl
L/S
My AL dy

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: