

Not withstanding  
11 Pp @ 3650/h  
Priming After Priming  
4 days

4 days

**INSURANCE: MSIG**

VEHICLE NO.: SGD 6525 J

✓  
x  
✓  
x  
✓  
✓

400d  
600d  
60d  
✓  
✓

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.