





SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 28/12/2020

User ID : CatherineLee

Section A - Accident Details	
Registration Number	SG5873C
Case Reference Number	BUS/11/20/5007
Registration Date	16/11/2017
Company Type	SMRT Buses Ltd
Make	MAN
Model	A95
Name of Driver	Bao Defu
Type of Accident	Head to Rear
Accident Date and Time	9/11/2020 11:19 AM
Accident Reported Date and Time	12/11/2020 9:49 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24108782
Special Instruction to ARC,if any	SG5873C-REAR RIGHT BODY CRACKED AND DENTED FBD2767M (TP) INSURED WITH NTUC
Prepared Date and Time	12/11/2020 1:50 PM
Chassis Number	WMAA95ZZ5G7003554
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,060.00	\$1,060.00
Total Spray Cost	\$772.00	\$602.00
Total Spare Part Cost	\$1,546.10	\$1,422.35
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$3,378.10	\$3,084.35
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	3.0	3.0
Prepared / Adjusted By	Jeong Choon Hwee	Sun Pin (LKK)
ARC / Surveyor Sign Off Date	12/11/2020 2:17 PM	13/11/2020 2:15 PM
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 28/12/2020

User ID : CatherineLee

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope			Quotation from AR				Adjusted by Surveyor, if applicable		
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.			\$1,060.00				\$1,060.00		
Total Labour			\$1,060.00				\$1,060.00		
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
TO PUTTY & RESPRAY			\$772.00				\$602.00		
Total Spray Painting & Panel Beating			\$772.00				\$602.00		
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
Total Other Costs									
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
			SMRT STICKERS	1.00	\$75.00	0.00	\$75.00	Replace	Replace / NEC
			60 KM/H STICKER	1.00	\$5.00	0.00	\$5.00	Replace	Replace / NEC
			FRP REAR LAMP COVER OS	1.00	\$975.00	10.00	\$877.50	Replace	Replace / CRU
6012636	VE		REVERSE LAMP BULB (A95 MAN)	1.00	\$235.00	10.00	\$211.50	Replace	Replace / CRA
6012635	VE		REAR LAMP BULB (A95 MAN)	1.00	\$245.00	10.00	\$220.50	Replace	Replace / CRA
6013467			REFLECTOR:FOR MAN A95 EURO 6	1.00	\$36.50	10.00	\$32.85	Replace	Replace / CRA
6013365			REFLECTOR,REAR:RIGHT MAN A95 E6	1.00	\$137.50	100.00	\$0.00	Replace	Repair X R
Total					\$1,709.00		\$1,422.35		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

1,422.35
1,060
602
3,084.35

PIP
\$3,084.35
3 days