

Claim Handling

[Task Transfer](#) [Exit](#)

▼ Accident MT/1110459

LOS SAL SUB

Policy No.	5095111957-03	Vehicle No.	SKD708R	GST Registration No.	200004767W
Certificate No.					
Policyholder Name	FRANK MARINE SERVICES PTE LTD			Policyholder NRIC	200004767W
Product Code	PRIVATE CAR INSURANCE	Cover Type	drivo CLASSIC	Loading	0
Contact No.(Mobile)	NA	Contact No.(Office)		Contact No.(Home)	
Email Address		Special Remark		eCode	No ▾
KFK	<input type="radio"/> No <input type="radio"/> Yes	TCA	<input type="radio"/> No <input type="radio"/> Yes	eCode Reason	
NCD Protection	No	NCD Entitlement(%)	40	Private Hire	No

▼ Accident Details

Report Date	17/11/2020 16:11	Accident Report Within 24 hrs	Yes	Accident Type	Collision - Head to Rear
Date of Accident	13/11/2020	Time of Accident hh:mm	20:00	Country of Accident	Singapore
Reporting Centre	NATIONAL ASSESSMENT CENTR	Orange Force	No	ICM No.	
Accident Location	CTE TWDS WOODLANDS NEAR BRADDELL EXIT				

▼ Total Excess Applicable

Excess Type	Per Accident	Windscreen Excess	100.00		
OD Standard Excess	600.00	TP Standard Excess	0.00	Driver is Covered?	Covered
YIED OD Excess	0.00	YIED TP Excess	0.00		
Additional Excess	0.00				
Total OD Excess Applicable	600.00	Total TP Excess Applicable	0.00		

▼ Benefits

▼ GST Registered Information

GST Registered	Yes	GST Registration Date	07/04/2003
GST Registration No.	200004767W	GST Status Verified	Yes
Modification History	17/11/2020 16:13:37 System changed GST Registration Date from 01/01/2015 to 07/04/2003 17/11/2020 16:13:37 System changed GST Status Verified from No to Yes		

▼ Policyholder Mailing Address

Address 1	5 LOYANG WALK	Address 2	SINGAPORE 508788	Address 3	
Address 4		Address Type	Singapore address	Post Code	508788
Unit No.		Related Policy Number	5095112356-03		

▼ OI Driver Info

Driver Name	Unnamed Driver	Driver Type	Unnamed Driver		
Unnamed driver Name	TEO ZIYANG (ZHAO ZIYANG)	Driver NRIC	S9028913F	Driver DOB	01/08/1990
Register Date of Driver License	11/11/2009	Driver Age	30	Driving Experience	11
Contact No.(Mobile)	96159368	Contact No.(Office)		Contact No.(Home)	
Address 1	35 LENGKOK MARIAM	Address 2	# CHANGI GROVE	Address 3	SINGAPORE 509136
Address 4		Address Type	Singapore address	Post Code	509136
Unit No.					
Does he own a Singapore Registered car?	<input type="radio"/> Yes <input checked="" type="radio"/> No	Driver Vehicle No.		Driver Insurer Company	

▼ Declaration

Breathalyser or Blood Test Reading?	0 mg	Any injury?	<input type="radio"/> Yes <input checked="" type="radio"/> No
Modification History			

▼ Investigation

Claim 002 OD-MD

▼ Claim Case Officer Zuraimie Bin Mantau

Claim Type	OD-MD	Insured Name	FRANK MARINE SERVICES PTE	Insured NRIC	200004767W
Contact No.(Mobile)		Contact No. (Home)		Contact No. (Office)	65430025
Email Address		OI Vehicle Number	SKD708R	TP Vehicle Number	SLG575D
Claim Description	SKD708R / SLG575D ON 13 Nov 2020			Name of Preferred Workshop	
Preferred Workshop Contact No. (Mobile)		Preferred Repair Option	income to assign workshop	Insured at report	Fully at resolved
Date Registered	17/11/2020 16:29	Claim Close Date		Date Received	17/11/2020 00:1
Report Taken By	LIEW SHAN HUI	Workshop Repairer		Total Loss but Repaired	

Print AK letter

OD Excess
Collected by
Workshop

Modification History

Special Claim Creation Approval

Approval Reason

Remarks

damage assessment Attachment

Vehicle Info

Vehicle Make	LAND ROVER	Vehicle Model	RANGE ROVER EVOQUE	Engine Capacity	
Date of Registration	31/10/2011	Classis No.	SALVA1AGXCH608367		
Towing Required *	<input checked="" type="radio"/> Yes <input type="radio"/> No	Vehicle in IDAC *	<input checked="" type="radio"/> Yes <input type="radio"/> No	Parallel Import *	<input type="radio"/> Yes <input checked="" type="radio"/> No
Type of Tender *	Own Damage	Assessor Name *	GUO QIANG	Survey Current Status	
IDAC/Workshop Name	NATIONAL ASSESSMENT CENTR	IDAC/Workshop Location	51 UBI AVENUE 1 #01-25 PAYA		
Windscreen Parts & Labour Cost		Total Loss *	<input type="radio"/> Yes <input checked="" type="radio"/> No		
Market Value(\$)		Scrape Value(\$)		Economical Repair Value(\$)	

REMARK:NO OF REPAIR DAYS:6 DAYS.1X FRT BUMPER PAD - UNCONFIRM.1X FRT LH FENDER PROTECTOR - REPLACE.1X FRT RH FENDER PROTECTOR - REPLACE.

Remark

Remark for Supplementary

Damage Listing

Find a Part	No.	Part No.	Description	Qty *	Repair Code *
root	1	32200101	NUMBER PLATE (FRONT)	1	Replace
Not Applicable	2	32200201	NUMBER PLATE BASE (FRONT)	1	Replace
ABS	3	16000101	BUMPER (FRONT)	1	Replace
ABSORBER	4	16002401	BUMPER CLIPS (FRONT)	6	Replace
ACCELERATOR	5	16004401	BUMPER NOZZLE (FRONT LEFT)	1	Unconfirm
ACTUATOR	6	16004402	BUMPER NOZZLE (FRONT RIGHT)	1	Unconfirm
ADVERTISEMENT STICKER	7	16005001	BUMPER REINFORCEMENT (FRONT)	1	Replace
AIR BAG	8	16001001	BUMPER BEAM (FRONT)	1	Replace
AIR BLOWER	9	16005901	BUMPER SPONGE (FRONT)	1	Unconfirm
AIR BOX	10	16003201	BUMPER GRILLE (FRONT)	1	Replace
AIR CHAMBER BOX	11	16004201	BUMPER MOULDING (FRONT)	1	Replace
AIR CLEANER	12	16004101	BUMPER LOWER SPOILER (FRONT)	1	Replace
AIR COMPRESSOR	13	16005501	BUMPER SENSOR (FRONT)	1	Replace
AIR CON	14	27100101	GRILLE (FRONT)	1	Replace
AIR CON (VAN)	15	27100801	GRILLE EMBLEM (FRONT)	1	Replace
AIR COOLER	16	41300101	SUPPORT PANEL (FRONT)	1	Replace
AIR DISTRIBUTOR	17	28500101	HORN (LEFT)	1	Replace
AIR FILTER	18	28500102	HORN (RIGHT)	1	Replace
AIR FLOW	19	27700101	HEAD LAMP (LEFT)	1	Replace
AIR GRILLE	20	27700102	HEAD LAMP (RIGHT)	1	Replace
AIR HORN	21	149001	BONNET	1	Replace
AIR INTAKE	22	149016	BONNET EMBLEM	1	Replace
AIR RESONATOR BOX	23	14903401	BONNET LOCK (LOWER)	1	Replace
AIR THROTTLE BODY AND SENSOR	24	112023	AIR CON CONDENSER	1	Replace
ALARM	25	112060	AIR CON FAN	1	Unconfirm
ALTERNATOR	26	344001	RADIATOR	1	Replace
ALUMINIUM PANEL - SIDE	27	344005	RADIATOR COWLING	1	Unconfirm
AMPLIFIER	28	344008	RADIATOR FAN	1	Unconfirm
ANTENNA					
ANTI ROLL					
APRON					
ARCH					
ARM REST					
ASH TRAY					
AUTO CLUTCH					
AUTO COOLER PIPE					
AUTO CRUISE MOTOR					
AUTO TRANSMISSION					
AXLE					

29	344031	RADIATOR SIDE GARNISH	2	Replace
----	--------	-----------------------	---	---------