

Accident Sketch Plan

SKETCH PLAN Tampines Ave 12 towards Tampines Ave 9



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the stated date and time, at the stated venue,
my vehicle 'A' SLJ 5689K was stationary before the
red light. Suddenly I felt an impact on the rear
portion of my stationary vehicle. Vehicle 'B' SLP 3513R
failed to stop hit onto my vehicle due to the impact all
the food inside my vehicle was spilled all over my
cushion.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature

Date & Time:


Driver's Signature
(If driver is not the policyholder)

Date & Time:

IDAC KAKI BUKIT (VAC)
23 Kaki Bukit Ave 4 #02-02
Singapore 415933
Tel: 67416697 Fax: 67492305
Email: varkh@idac.com.sg

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.: 16 NOV 2020

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo

