



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL

Ref : CS/AGI20012576/Kvf3q2

(BUDGET DIRECT INSURANCE)

190 CLEMENCEAU AVENUE #03-01
SINGAPORE SHOPPING CENTRESINGAPORE
239924

Date : 01-12-2020



Code : AGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGR 4074H	Veh. Inspected	GBD 9587U
Policy No.		Coverage (\$)	0.00
Claim No.	C10007922/LA	Excess (\$)	0.00
Assign From	IVY RATILLA	Assign Date	16/11/2020

2. Vehicle Particulars & Condition

Make & Model	NISSAN CABSTAR (M)	c.c	2953
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	JN1SC2F24Z0857350	Colour	SILVER
Odometer	164070	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/75 R15	KENDA	9 mm
L/H Front Tyre	195/75 R15	KENDA	9 mm
R/H Rear Tyre	165 R15X8 (D)	CONDOR	7/7 mm
L/H Rear Tyre	165 R15X8 (D)	CONDOR	7/7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	10/11/2020	Inspection Date	17/11/2020
Survey held at	AE AUTO PTE LTD 160 SIN MING DRIVE #06-01 SIN MING AUTOCITY SINGAPORE 575722		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	-----------------------