



Your Ref: 20/20/20/VC05/023712

Date: 25th November 2019

Our Ref: CS1/LPC20012583/R1qf3e2

M/s Lonpac Insurance Bhd
300 Beach Road
#17-04/07 The Concourse
Singapore 199555
(The Motor Claims Department)

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: XD 4106Y
INSURED VEHICLE: YN 5079X
ACCIDENT DATE: 26/09/2020

We thank you for your instruction on 16/11/2020.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of XD 4106Y from M/s Constant Appraiser Services.
- b) Colour damaged vehicle photographs of XD 4106Y.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: XD 4106Y
Make & Model	: Scania P380CB8X4MHZ
Year of Registration	: 2010
Chassis Number	: YS2P8X40002043890
Engine Capacity	: 11705 cc

2. We recommend that the repairs of the entire damage require about 5 (Five) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.