

C64/TII 20012506/DPs3

ASSIGNMENT

COE July 2030

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_


Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: FBE 8086A Yr Regn: Sept 2010

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Yamaha T135 c.c. 135

Colour: Black / Blue A/C: Insured / Std / NI / NA

Sp. Reading: 22238 T/Radio: Insured / Std / NI / NA

Eng/No: 5YP302809

C/No: 5YP302809

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 70/90 R17

R: 80/90 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Dunlop

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 2 mm R/Bal. 2 mm

L/Bal. \_\_\_\_\_ mm L/Bal. \_\_\_\_\_ mm

D.O.A. 11/11/2020 D.O.A. 17/11/2020

Survey held at SG 98 Majar AMK

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TII SHA 6115M

15/11/2020 jmg 1/s 27001 with 5 days 2 m

Date/Time, File Pass to?

☐

Prel. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Report Format:

Lump Sum / LB: (\$ \_\_\_\_\_)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee:

☐

Site Insp (\$ \_\_\_\_\_)

☐

Interview (\$ \_\_\_\_\_)

☐

Tech. Invs (\$ \_\_\_\_\_)

☐

Weekend (\$ \_\_\_\_\_)

Survey Fee:

Transportation:

S+RS \$ \_\_\_\_\_

Photos

Others

TOTAL