Surveyor: NAZ | REF: AIG

ASSIGNMENT

Date:

Estimated Cost:

CC / TP / WS / YP RES / OD RES / EVA / INV / MV

Insured Vehicle No:

Workshop Info:

Excess:

Veh No: FBK 5719X | Yr Regn: 30 OCT. 2015

Type: M.Car / M.Cycle / BUS / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: HONDA CB 400 | cc: 399

Colour: BLUE | A/C: Insured / Std / Nil

Sp Reading: 113,805 | T/Belp: Insured / Std / Nil

Engine:

Chassis: NC421602752

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Jammed / Locked / Burnt or

Brake: Jammed / Locked / Burnt or

Wheels: Nil / St Rim / STD / A Rim or

Tyre Size: F: 120 / 60 R17 | R: 160 / 60 R17

BS / CUR / EXNOVA / GY / FS / LZA / MC / OHTSU / PIR / SUMI / TOYO / YOKO or TIMSUM

Tread: F/Bal: Y mm | R/Bal: Y | O/Bal: - mm | O/Bal:

DOA: 6/11/2020 | DOS: 4/2/2021

Survey Point at: BIKE PRODUCTION

Det. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Tyre / U/C / Chassis frame / Body Structure / Models Code

MGL/S

N/S | O/S

Vehicle: IN / OUT

Action / Instruction

COE Rebate $3,079.00
Repair Limit 9K. Repairer informed

Days Of Repair:

Resurvey No. of Trip:

Prelim. Report

Final Report

Add Fee: Site Insp / Interview / Tech. Inv / Weekend

Survey Fee: