

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/11/2020 10:50
Date Of Accident	09/11/2020 08:55
Exact Location Of Accident	PASIR RIS DR 6 78071 • BLK 446
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SBS6563D
-----------------------------	----------

Insured/Policyholder

Name Of Registered Owner	GO AHEAD SINGAPORE PTE LTD
Co Reg No	2XXXXX900C
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-63847169

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	CITARO O530-6.4 L AT TURBO ABS (A)
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	BUS

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	D-19094111MFBP
Cover Note Number	

Driver

Name of Driver	LEE KOK HIN
NRIC No	SXXXX624I
Date Of Birth	16/09/1954
Occupation	OUTDOOR
Date Of Driving Pass	02/11/1976
Driving Experience	44 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96161861
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	524 BEDOK NTH ST 3 #03-382
Postcode	460524
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	10

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	PASIR RIS NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 1 PASIR RIS DRIVE 4 , POSTCODE: 519457 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-5852999 - FAX NO: 65855261
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS DRIVING GO-AHEAD SINGAPORE SERVICE 358 [SBS6563D] ON THE ABOVE-MENTIONED DATE & TIME. ON REACHING THE ABOVE-MENTIONED LOCATION, A BLUE COMFORT-DELGRO TAXI [SHC1268C] STOPPED INSIDE TO BOARD PASSENGER SO I STEERED RIGHT SLIGHTLY TO AVOID. HOWEVER, SHC1268C'S DRIVER SUDDENLY OPENED THE FRONT DOOR & GRAZED AGAINST THE MIDDLE LEFT BODY PANEL OF MY BUS. I ALIGHTED FROM MY BUS WANTING TO EXCHANGE PARTICULARS WITH SHC1268C'S DRIVER BUT IT FLED THE SCENE.

Attachment(s)


Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	DIFFERENT FORMAT
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHC1268C
Vehicle Make/Model/Colour	BLUE TOYOTA PRIUS HYBRID 1.8 CVT
Details Of Properties	FRONT RIGHT DOOR
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	

Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Sketch Plan



POLICE REPORT 3



**SINGAPORE
POLICE FORCE**



T/20201111/2041

3 of 3

Report No. T/20201111/2041

Police Station Of Origin:
Pasir Ris N.P.C
1 Pasir Ris Drive 4 #01-01 SINGAPORE
519457
Tel No: 1800-5852999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

G /

Sgt 3 AMAL NADHIRAH BINTE JUFRI

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

11/11/2020 12:16

Officer In Charge Of Case:

TP / HRT /

Sr Staff Sgt NEO ZHI YUAN

Contact No.: 65476079

Classification Of Case:

Authentication Stamp

NP168



POLICE REPORT 2



**SINGAPORE
POLICE FORCE**



T/20201111/2041

Police Station Of Origin:
Pasir Ris N.P.C
1 Pasir Ris Drive 4 #01-01 SINGAPORE
519457
Tel No: 1800-5852999

2 of 3

Report No. T/20201111/2041

CONTINUATION OF REPORT

Brief Details.

On the 9/11/2020 at about 8.57am, I(SBS6563D) was driving bus service 358, along Pasir Ris Dr 6, when I approached a bus stop near to B/446 Pasir Ris Dr 6. As I was approaching the stop, there was a blue taxi (SHC1268C) suddenly went into the bus stop to pick up a passenger. I managed to steer to my right to avoid a collision with the taxi. However, the driver suddenly opened its door, and it caused my rear left wheel fender to be grazed. At that point of time, I alighted the bus to check on the damages, and wanted to take the company phone to report about the accident, however the driver drove off even before I could ask for his particulars.

The driver is a male in his 60s. I am not injured. None of my passengers are injured.

POLICE REPORT 1



**SINGAPORE
POLICE FORCE**



T/20201111/2041

Police Station Of Origin:
Pasir Ris N.P.C
1 Pasir Ris Drive 4 #01-01 SINGAPORE
519457
Tel No: 1800-5852999

1 of 3

Report No. T/20201111/2041

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 11/11/2020 12:16		Vide Report No.:		Station Diary No.: 31	
Informant's Particulars					
Name of Informant: LEE KOK HIN			Address: APT BLK 524 BEDOK NORTH STREET 3 #03-382 SINGAPORE 460524		
ID Type / ID No.: NRIC NO / S0164624I			Contact No.: Home/Office: Mobile: 96161861		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 66	Date of Birth: 16/09/1954	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: Bus driver			Driving Licence Information: Class: 3,4 Date of Expiry:		

General Information of the Accident					
Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 09/11/2020 08:55	Type of Location: BUS STOP	
Location: PASIR RIS DRIVE 6					
Weather: Clear		Road Surface: Dry		Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction				Anyone conveyed by ambulance: No	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SBS6563D	Bus/Coach/Minibus				Slightly Damaged	13
SHC1268C	Car				Slightly Damaged	0

Accident Photo



Accident Photo

