





PRE-REPAIR INSPECTION REPORT				
LONPAC INSURANCE BHD		Ref: CS3/LPC20012639/Esf3e2		
300 BEACH ROAD		Date: 20-11-2020		
#17-04/07 THE CONCOURSESINGAPORE 199555		Code: LPC2		
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	GV 6031Y	Veh. Inspected	SMS 5345T	
Policy No.		Coverage (\$)	0.00	
Claim No.	20/20/20/VC05/023910	Excess (\$)	0.00	
Assign From	KENNY LIM	Assign Date	17/11/2020	
2. Vehicle Particulars & Condition				
Make & Model	HONDA VEZEL	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2020	
Chassis No.	RU11322076	Colour	BLACK	
Odometer	47632 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	DUNLOP	4 mm	
L/H Front Tyre	215/60 R16	DUNLOP	4 mm	
R/H Rear Tyre	215/60 R16	DUNLOP	4 mm	
L/H Rear Tyre	215/60 R16	DUNLOP	4 mm	
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.			
5. General Information				
Accident Date	13/11/2020	Inspect Date / Time	17/11/2020 (02:05 PM)	
Survey held at	GARAGE 13 PTE LTD 8 KAKI BUKIT AVE 4 #03-46 PREMIER 415875 SINGAPORE.			
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

Report Ref No. CS3/LPC20012639/Esf3e2

Inspected By



CHEN TSUE YEE

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or
relying on this Report, in whole or in part, does so at his or her own risk.