

12/11/2020

ASS. REC. BY:

REF: CS/LPC20012691/Kvd3

Special Instruction:

Surveyor: KENNETH

ASSIGNMENT (Office)

From (Person): ONG LI LI

of LPC

Date/Time: 18/11/2020@10.23AM

Estimated Cost:

Bill to:

☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMG 8289R

Insured:

at Workshop m/s

K.KIM HIN AUTO

Tel: 6452 7018

of 160 SIN MING DRIVE # 02-20

Policy No:

Claim No: 20/20/20/VP05/023904

Sum Insured:

Excess: NIL

Make of Veh:

D.O.A. 13/11/2020

(Client's Record)

CA / ☒ REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 10.32AM@18/11/20

Person Contacted: SANDRA

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (☒) Estimate
	SMG 8289R-X
18/11/20	Revert to Li Li by email
23/11/20	Rece authorise repair from Li Li by email
23/11/20	Informed Simon C/A, excess NIL
28/1/21	Final fig \$5490.95 confirmed (Red 4819.25.46%)