ASS. REC. BY:	0012681/KV C
15000001	SIGNMENT
From: Date: Date:	Veh No: SMG 8289RV: 2000 08 17
To Inspect Vehicle No:	Truck / Traffer or
at Workshop m/s  of  Insured:  Policy No.  Claims No.  Sum Insured:  Excess:	Colour M. P. White A/C: Insured / Std / NI / NA  Sp. Reading 83863 T/Radio: Insured / Std / NI / NA  Eng/No:  C/No:  SJV = E A J / / U / 473633  Gen. Cond.: Good / Fair / Poor / Burnt
(Client's Record)  Make of Veh:  (Policy Condition)	Steering: Inorder / Jammed / Leaked / Burnt or Brake: Inorder / Jammed / Leaked / Burnt or Modi: NII / S/RIm / STO A/RIm or Tyre Size: 215/60R17
Remark: The veh had commenced its repair at the time of inspection.  Bal. or Market Value: £ 52k	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or  Front
IDAC Accident Rport: Consistent?: Yes or No GIA / PR Seen: Consistent?: Yes or No Est. Repairs: O5 days Res.: Yes or No Lum Sum: I. B.   26 % 3 Val.: Yes or No	R/Bal. 4 mm R/Bal. 5 mm  L/Bal. 4 mm L/Bal. 5 mm  D.O.A. 13/11/20 D.O.I. 18/11/2020  Survey held at
Date: Person Contacted:  Date / Time   Action / Instruction   Repair Said   1-B .,00 2ns	Des. of Damages Fit Rear I O/S I N/S I U/C I Rooftop or  The U/C I Chassis frame I Body Structure affected due to collision.  Parts aveilable
28/1 \$ 5496.83 Confirmed (Red 514)  4/2/21 Kenneth re-confirmed \$5154 (Red 514)	4819.25,46%)
	survey No. of Trip: 1 Survey Fee:
2) 28/1/21-Typist  Report Format: OD  Lump Sum / I.B.I: (\$ 5154	Transportation:  Site Insp (\$ )S + RSSI  Interview (\$ )_Finals  Tech Invs (\$ )_Others  Weekend (\$
	TOTAL

•

### > Back to OneMotoring

**Enquire PARF/COE Rebate for Registered Vehicle** 

Vehicle Owner Particulars				
Owner ID Type:	Singapore NRIC			
Owner ID: Vehicle Details	141G			
Vehicle No.:	SMG8289R No			
Vehicle to be Exported:				
Intended Deregistration Date:	16 Nov 2020			
Vehicle Make:	NISSAN			
Vehicle Model:	QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR			
Primary Colour:	White			
Manufacturing Year:	2015			
Engine No.:	HRA2184820A			
Chassis No.:	SJNFEAJ11U1473663			
Maximum Power Output:	85.0 kW (113 bhp)			
Open Market Value:	\$18,413.00			
Original Registration Date:	30 Sep 2015			
First Registration Date:	30 Sep 2015			
Transfer Count:	1			
Actual ARF Paid: Intended PARF Rebate Details	\$13,413.00			
PARF Eligibility:	Yes			
PARF Eligibility Expiry Date:	29 Sep 2025			
PARF Rebate Amount: Intended COE Rebate Details	\$9,389.00			
COE Expiry Date:	29 Sep 2025			
COE Category:	A - Car up to 1600cc & 97kW (130bhp)			
COE Period(Years):	10			
QP Paid:	\$57,498.00			
COE Rebate Amount:	\$27,998.00			
Total Rebate Amount:	\$37,387.00			

The information contained herein is correct as at 16 Nov 2020

#### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

aforesaid.			
	ACCIDENT STATEMENT		
Date Of Report	16/11/2020 18:17		
Date Of Accident	13/11/2020 15:10		
Exact Location Of Accident	ADAM RD (SLIP RD AT JUNC OF ADAM RD FOOD CENTRE)		
Country/State of Loss	SINGAPORE		
THE STATE OF THE S	DETAILS OF OWN VEHICLE		
Vehicle Registration Number	SMG8289R		
Insured/Policyholder			
Name Of Registered Owner	CHNG POH YING		
NRIC No	SXXXX141G		
Email Address	PROPERTY6868@YAHOO.COM		
Mobile Phone No	(LOCAL) +65-82223977		
Alternative Phone No	OFFICE-82223977		
Vehicle Particulars			
Manufacturer	NISSAN		
Model	QASHQAI-1.2 DIG-T CVT ABS 2WD 5DR (A)		
Exact Purpose for which vehicle was being used at time of accident	t e e e e e e e e e e e e e e e e e e e		
Are you claiming under your own insurance policy for repair to your vehicle?	YES		
If No, Please state action to be taken			
Vehicle Category	PRIVATE CAR		
Insurance Company			
Name of Insurance Company	LONPAC INSURANCE BHD		
Type Of Coverage	COMPREHENSIVE		
Fleet Policy	NO		

Z20VP05026110 Policy Number

Cover Note Number

#### Driver

Name of Driver CHNG POH YING NRIC No SXXXX141G Date Of Birth 25/01/1978 **INDOOR** Occupation Date Of Driving Pass 14/07/2004 **Driving Experience** 

16 YEARS AND 3 MONTHS

**FEMALE** Gender

(LOCAL) +65-82223977 Mobile Number

Fax Number

Contact Number OFFICE-82223977

**EMail Address** PROPERTY6868@YAHOO.COM Address

53 GRANGE ROAD #03-02

Postcode

249565

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

**OWNER** 

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle) involved in the accident

2

Was any body injured in the Accident?

YES

Was any injured conveyed to hospital by

NO

ambulance?

YES

Was any other material or property damaged? I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

**Details of Police Action** 

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

**Circumstances of Accident** 

PLEASE REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

**DETAILS OF OTHER VEHICLE PROPERTY 1** 

Vehicle Registration Number

SHD2156E

Vehicle Make/Model/Colour

TOYOTA

**Details Of Properties** 

Vehicle Category

TAXI

Name of Driver

LEE KAR KHEW

NRIC/Passport Number

SXXXX113I

Contact Number

96849125

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1** 

Name

LEE KAR KHEW

Approximate Age
Injuries Sustain
Injured person in which vehicle?
Were seat belts worn?
Was this injured conveyed to hose

Was this injured conveyed to hospital by ambulance?

Address

Postcode

BUMP ON RIGHT SIDE OF FOREHEAD SHD2156E

YES

NO

#### Sketch Plan Pg. 1

#### SKETCH PLAN

#### **IMPORTANT NOTICE**

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

3:470

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIEFIN No.

SKETCH PLAN	
A SMG 8287 P. P. SHD 2156 E	
DESCRIBE CIRCUMSTANCES OF THE ACCIDENT	
I was making a left turn at the Adam Food Center cross junction clip road.	
Whon entering the slip road, there was a taxi in	
fort of me	
I was looking at the traffic on the sid right side	
and assumed that the tax had moved off as the	
front of me. oncoming  I was looking at the traffic on the side right side  and assumed that the tax had moved off as the  bus approching the slip road was very far off.	
The taxi did not move off and as I rolled forward my hood hit the back off the taxi	
my hood hit the back of the taxi	
	<i>88</i>
DECLARATION	
1/We declare the foregoing particulars are true in every respect.    TEL:   TEL	

(If driver is not the policyholder)

Date & Time:

Date & Time:

Company Chop (if applicable)



## 金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20, Sin Ming AutoCity, Singapore 575722 Tel: 6452 7018 Fax: 6458 3895

Email: service@kkimhin.com.sg

Your Reference : Z20VP05026110

Accident Date : 13-Nov-2020

No.: 31529

Date: 18-Nov-2020

Our Ref : 020551 / QUEK

LONPAC INSURANCE BHD 300 BEACH ROAD

#17-04/07 THE CONCOURSE Singapore 199555

PAGE: 1

Not Nothaired Vising & Rearry After Paint 5

ESTIMATED COST OF REPAIR FOR NISSAN QASHQAI 1.2 DIG-T CVT(2015) SMG8289R 

1	рс	front bumper front bumper tow cover front bumper side retainer	@	s\$ 19.00	Bu 350.00 c No 25.00 c Dri 38.00 c
10	pcs pc	(LH/RH) front bumper clips front bumper sponge - big	@	S\$ 1.50	M 15.00 c CM 125.00 c 7
	-	front bumper sponge - small (LH/RH)	@	S\$ 75.00	150.00 c X
	pc pcs		0	S\$ 75.00	10c320.00 c \$ 1 150.00 c
		· · · ·		mg car.	135.00 c x 320.00 c — 45.00 c — May 6.00 c — 530.00 c —
4		front grille clips	@	S\$ 1.50	m 6.00 c
1 2 1 1		bonnet hinges (LH/RH) bonnet lock bonnet lock pull lever	@	S\$ 60.00	7 120.00 c × 7 120.00 c × 7 75.00 c ×
13	pes	bonnet insulation clips bonnet outer seal	@	S\$ 2.00	
1 2	рс	bonnet inner seal	a	S# 1/ 00	M 55.00 c →
		bonnet side stopper (LH/RH) front fender wheel arch c/J/Bn			
		<pre>garnish (LH/RH) headlamp assy (LH/RH) headlamp lower bracket(LH/RH)]</pre>	a	S\$385.00	770.00 c 760
	r ~ ~		V	ng	iom

Con't Page 2 ...

AUTO PTE LTD

CO. REG. NO: 199402370D GST NO: M2-0123250-3

## 金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,

Sin Ming AutoCity, Singapore 575722

Tel: 6452 7018 Fax: 6458 3895 Email: service@kkimhin.com.sg

Your Reference : Z20VP05026110

Our Ref: 020551

Page: 2

No.: 31529

1 pc front support panel рс air con condenser

radiator assy ре

radiator top mounting bracket рc

рс radiator air guide - RH

radiator air guide - LH рс

turbo cooler - RH рс

transmission oil cooler рс

1 pc washer tank

washer tank motor] рс

N 320.00 c **%** 580.00 c **1** 480.00 c n 70.00 c x **cm** 40.00 c CM 60.00 c x 1,350.00 c X

**S** 390.00 c

**か** 140.00 c X

7,353.00

Add 15%: 1,102.95

8,455.95

front number plate 1 pc

1 pc radiator coolant

To remove, cut out damaged parts, panel beating, welding, align,

refix and to renew affected parts.

To remove aircon condenser, pipes and driers. Vaccum and recharge gas

To putty and respray on affected portions.

To focus headlamps. To check front wiring and lighting operation.

 $cm_{40.00 \text{ sn}}$ Ma 40.00 sn 30/2

600.00 50d

100.00

800.00 600

50.00 201

Total:

\$\$10,085.95 =========

Singapore Dollars Ten Thousand and Eighty Five and Cents Ninety Five Only

Note: Amount quoted above is subject to prevailing ST at time, of tax invoice.

the Repairer of the following:

- · To resurvey before/after spray painting
- . To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- . Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Dale:



CO. REG. NO: 199402370D GST NO: M2-0123250-3

## AUTO PTE LTD

# 金興(襲)汽車私人有限公司

160 Sin Ming Drive, #02-20,

Sin Ming AutoCity, Singapore 575722

Tel: 6452 7018 Fax: 6458 3895 Email: service@kkimhin.com.sg

Your Reference: Z20VP05026110

Accident Date : 13-Nov-2020

: 020551 / JEROME

No : 31529 Date : 23-Nov-2020

LONPAC INSURANCE BHD 300 BEACH ROAD #17-04 / 07 THE CONCOURSE

Singapore 199555

Our Ref

SUPPLEMENTARY ITEMS FOR NISSAN QASHQAI 1.2 DIG-T CVT (2015) SMG8289R

1 pc engine under cover

195.00

195.00

Add 15%: 29.25

Total 224.25

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.