

ASS. REC. BY: Steve REF: CS3/AIG 20012731/ETf3

ASSIGNMENT

From: PRS Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: F82 1170Y Yr Regn: 25 Jul 2019
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Yamaha MT-15 c.c. 155
 Colour: Blue A/C: Insured / Std / NI / N
 Sp. Reading: N/A T/Radio: Insured / Std / NI / N
 Eng/No: _____
 C/No: ME 1RG5913K0007329
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 120/70R17
 R: 149/70R17

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front R/Bal. 5 mm Rear R/Bal. 5 mm
 L/Bal. _____ mm L/Bal. _____ mm
 D.O.A. 13/11/20 D.O.I. 19/11/20
 Survey held at Garage 13
 Des. of Damages: (Frt) / Rear / (O/S) / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction
	No GIA report
	submit DAR report

Date/Time, File Pass to? : Prel. Report
 : Final Report
 Date/Time, File Return to? _____

Days Of Repair: 4
 Resurvey No. of Trip: _____

Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech. Invs (\$ _____)
 : Weekend (\$ _____)

Survey Fee:	
Transportation:	
\$ + RS. \$	
Photos	
Others	
TOTAL	

Rep. Form: _____
 Lump Sum / L.E.I. / _____

(1) Busted (2) Distorted (3) Cracked (4) Cut (5) Scratched
 (6) Bent (7) Mangled (8) Rusted (9) Buckled (10) Broken (11) Necessary
 (12) Missing (13) Torn (14) Unconfirmed (15) Not Working

FOR MOTORCYCLE

1. Replace (✓) 2. Repair (✓) 3. Check (✓)
 4. Not Correct (N/C)

Vehicle No: **F82 1170 Y**

Motorcycle

NAC	INC	Item	CON	AC	Qty
3001	991886	Front Number Plate	BT	✓	
3001	995065	Front Tyre	CUT	✓	
3002	995095	Front Rim		✓	
3003	994872	Front Tyre Rim Spoke	BR	✓	
3004	991771	Front Fender Wheel Guard	BT	✓	
3005	991283	Front Brake Disc		✓	
3006	991281	Front Brake Caliper		✓	
3007	991785	Front Fork Assy	BT	✓	2
3008	991787	Front Fork Inner Tube			
3009	991789	Front Fork Outer Tube			
3010	991167	Front Fork Bracket	BT	✓	
3011	991182	Front Fork Oil Seal			
3012	991174	Front Fork Garnish			
3013	992376	Front Headlamp Rim	CUT	✓	
3014	992328	Front Headlamp		✓	
3015	992337	Front Headlamp Bracket	BT	✓	
3016	992345	Front Headlamp Fairing			
3017	992130	Front Windshield			
3018	992134	Front Wing Mirror	CUT	✓	2
3019	995245	Front LH Signal Lamp			
3020	995246	Front RH Signal Lamp	CUT	✓	
3021	992556	Meter Casing			
3022	992553	Meter Assy	CUT	✓	
3023	991019	ERP Bracket			
3024	991020	ERP Unit			
3023	992446	Ignition Switch			
3024	992442	Ignition Key Assy			
3025	990706	Cowling Stay			
3026	994470	Steering Stem			
3027	994427	Steering Cone	N/C	✓	
3028	992299	Handle Bar	BT	✓	
3029	992312	Handle Bar Switch			
3030	992310	Handle Bar Grip			
3031	995184	Handle Bar Balancer LH	CUT	✓	
3032	992300	Handle Bar Balancer RH	CUT	✓	
3033	992179	Fuel Tank			
3033	990438	Brake Reservoir			
3034	990621	Clutch Lever	BR	✓	
3035	992293	Hand Brake Lever	CUT	✓	
3036	991119	Side Fairing	CUT	✓	2
3037	994220	Side Fairing Top Garnish			
3038	994219	Side Fairing Inner Garnish			
3039	991118	Fairing Shield			
3040	992047	Front Top Fairing Inner Garnish			
3041	991123	Fairing Top Garnish			
3042	990538	Center Fairing	CUT	✓	2
3043	993378	Rear Fairing			
3044	991121	Fairing Stopper			
3045	991117	Fairing Lower	CUT	✓	
		Helmet	CUT	✓	

NAC	INC	Item	CON	AC	Qty
3046	995074	Radiator			
3046	992738	Radiator Cowling			
3046	994146	Seat Assy bar, RH	CUT	✓	
3047	990915	Engine Crash Bar			
3048	990928	Engine Guard			
3049	990219	Battery			
3049	990224	Battery Cover			
3049	990223	Battery Bracket			
3049	991144	Foot Brake			
3050	991154	Front Foot Rest			
3051	991779	Front Foot Rest Bracket			
3052	994269	Side Stand			
3053	992549	Main Stand			
3054	990615	Clutch Engine Cover			
3055	992478	Kick Starter Rubber			
3056	992477	Kick Starter Lever			
3057	991145	Foot Gear Shifter			
3058	993500	Rear Foot Rest			
3059	993501	Rear Foot Rest Bracket			
3060	992581	Exhaust Muffler Heat Shield	CUT	✓	2
3061	991058	Exhaust Muffler Assy			
3062	993719	Rear LH Shock Absorber			
3062	993720	Rear RH Shock Absorber			
3062	995065	Rear Tyre			
3063	991200	Rear Rim			
3064	994872	Rear Tyre Rim Spoke			
3065	993474	Rear Fender Wheel Guard			
3066	993443	Rear Fender Mudflap			
3067	992940	Rear Brake Disc			
3068	992936	Rear Brake Caliper			
3069	995236	Rear Spocket			
3070	990585	Chain			
3071	990580	Chain Guard			
3072	994530	Swing Arm			
3073	993819	Rear Sub frame			
3073	995245	Rear LH Signal Lamp	CUT	✓	
3074	995246	Rear RH Signal Lamp			
3075	995251	Rear Taillamp			
3075	993626	Rear Number Plate	CUT	✓	
3076	994192	Side Box			
3077	992927	Rear Box			
3078	992928	Rear Box Bracket			
3079	991328	Emblem			
3079	990247	Sticker			

No of Items: _____

Assessor: _____

4 repair days