

ASS. REC. BY: Sun Pin

REF:

NTUC

NS/INC20012735/Qcd3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SMB 8035Hat Workshop m/s SMRT

of _____

Insured: GBC 1458SPolicy No. 5114309406


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SMB8035H Yr Regn: 05/10/2015Type: M.Car / M.Cycle / ☒ Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: MAN NG 363F c.c. 10518Colour: Multicolour A/C: Insured / Std / NI / NASp. Reading: 59168 T/Radio: Insured / Std / NI / NAEng/No: -C/No: WMAA24 ZZOF7002745Gen. Cond: Good / ☒ Fair / Poor / BurntSteering: In order / ☒ Jammed / Leaked / Burnt orBrake: In order / ☒ Jammed / Leaked / Burnt orModi: Nil / S/Rim / ☒ STD A/Rim orTyre Size: F: 215 / 70 R22-5R: 215 / 70 R22-5

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Firenza

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 06/11/2020 D.O.I. 12/11/2020Survey held at SMRTDes. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

SUN PIN CONFIRMED L/S \$7,350; 5 DAYS

(RED \$6,590.50, 47%)

Date/Time, File Pass to?

☐ : Preli. Report1) _____
Date/Time, File Return to?☐ : Final Report

2) _____

Days Of Repair: 5Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL

Report Format: TPLump Sum / L.S. (\$ \$7,350.00)Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	292D
Vehicle Details	
Vehicle No.:	SMB8035H
Vehicle to be Exported:	No
Intended Deregistration Date:	16 Nov 2020
Vehicle Make:	MAN
Vehicle Model:	NG 363F (A24)
Primary Colour:	Multicolor
Manufacturing Year:	2014
Engine No.:	50340161684008
Chassis No.:	WMAA24ZZ0F7002745
Maximum Power Output:	-
Open Market Value:	\$443,406.00
Original Registration Date:	05 Oct 2015
First Registration Date:	05 Oct 2015
Transfer Count:	0
Actual ARF Paid:	\$0.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Rebate Amount:	\$0.00
Total Rebate Amount:	\$0.00

The information contained herein is correct as at 16 Nov 2020

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/11/2020 13:56
Date Of Accident	06/11/2020 11:35
Exact Location Of Accident	TRAFFIC JUNCTION OF WOODLANDS AVENUE 3 AND WOODLAN
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMB8035H
Insured/Policyholder	
Name Of Registered Owner	SMRT BUSES LTD
Co Reg No	1XXXXX292D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	MAN
Model	MAN NG 363F (A24)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category BUS

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	D-20095488MFBP
Cover Note Number	

Driver

Name of Driver	S GOVINDHARAJ A/L SHANMUGAM
Passport No/FIN	GXXXX604Q
Date Of Birth	07/02/1965
Occupation	OUTDOOR
Date Of Driving Pass	26/09/2005
Driving Experience	15 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address NO ADDRESS

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 2

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 10

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

At around 1137 hours, I just came out from Woodlands Interchange and was starting on my 4th trip. I had stopped my bus before the traffic light junction of Woodlands Avenue 3 and Woodlands Avenue 5. The traffic light was red, and my bus was stationary with hand brake engaged while waiting for the traffic light to turn left. Suddenly, I heard a knocking sound. I checked my paxs (around 10 paxs onboard) and no one was injured or anything. I alighted to find one lorry (GBC1458S) had collided onto the rear portion of my bus. The rear bumper and rear engine cover of my bus was dented, and the rear right signal light cover was broken. The lorry front windscreen had cracked, and its front body was damaged. No other injury reported. My bus was stationary at the point of Accident. That is all.

Attachment(s)

Are accident photos available for attachment? NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT

Was there any video captured by Car Camera? YES

Remarks/ Reasons: PENDING DOWNLOAD

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBC1458S

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

SKETCH PLAN

SMB 8035H

pax = 10


Bus/11/20/7006

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

[Signature]


Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Traffic junction of Woodlands Avenue 3 and Woodlands Avenue 5

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672


Date Generated : 12/11/2020

User ID : GohKK2

Section A - Accident Details

Registration Number	SMB8035H
Case Reference Number	BUS/11/20/7006
Registration Date	5/10/2015
Company Type	SMRT Buses Ltd
Make	MAN
Model	MAN NG 363F (A24)
Name of Driver	S. Govindharaj A/L Shanmugam
Type of Accident	Head to Rear
Accident Date and Time	6/11/2020 11:37 AM
Accident Reported Date and Time	6/11/2020 1:15 PM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC, if any	SMB8035H-REAR PORTION GBC1458S (TP) INSURED WITH NTUC
Prepared Date and Time	12/11/2020 9:58 AM
Chassis Number	WMAA24ZZ0F7002745
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$2,650.00	\$0.00
Total Spray Cost	\$528.00	\$0.00
Total Spare Part Cost	\$7,551.61	\$0.00
Total Other Cost	\$300.00	\$0.00
TOTAL COST	\$11,029.61	\$0.00
Lump Sum Total	\$11,050.00	\$0.00
Number of Repair Days	6.0	
Prepared / Adjusted By	Kok Khoon Goh	
ARC / Surveyor Sign Off Date	12/11/2020 10:19 AM	
Signature		x
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 12/11/2020

User ID : GohKK2

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$2,650.00	2120
Total Labour	\$2,650.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$528.00	446
Total Spray Painting & Panel Beating	\$528.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	\$300.00	X
Total Other Costs	\$300.00	

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
			REFLECTOR STICKER BUMPER	1.00	\$75.00	0.00	\$75.00	Replace	/NRC
6011407	Body		DOOR,ENGINE:REAR,MAN A22 'C' SERIES	1.00	\$1,625.00	10.00	\$1,462.50	Replace	/CRY
6011408	Body		BUMPER,REAR,CENTRE,MAN A22 'C' SERIES	1.00	\$1,625.00	10.00	\$1,462.50	Replace	/CRY
6010298			LAMP,STOP:LED (MAN BUS)	1.00	\$1,141.70	10.00	\$1,027.53	Replace	/CRA
6010299			SIGNAL LAMP LED	1.00	\$1,274.10	10.00	\$1,146.69	Replace	/CRY
6010062	Body	F01001-CW273	COVER:REAR TAIL LAMP,RH,FOR MAN A22 BUS	1.00	\$974.70	10.00	\$877.23	Replace	/CRY
6010463	Body	S01001-CW006	FRAME,REAR BUMPER,FOR MAN A22 BUS	1.00	\$1,423.20	10.00	\$1,280.88	Replace	/BT
6010372	Body	4001F09-ACCE5021	PANEL,REFLECTOR:REAR,LH,FOR MAN BUS	1.00	\$107.00	10.00	\$96.30	Replace	/CRA NRC
6010373	Body	4001F09-ACCE5020	PANEL,REFLECTOR:REAR,RH,FOR MAN BUS	1.00	\$107.00	10.00	\$96.30	Replace	/CRA
6010412	Body	4001G01-GSP438	SPRING,GAS:500N,FOR MAN NL320F (A22)	1.00	\$241.50	10.00	\$217.35	Replace	/BT
6009375	VM		RETAINER:MALE & FEMALE,REAR LID,MAN BUS	2.00	\$74.80	10.00	\$134.64	Replace	?
			STICKER SMRT	1.00	\$75.00	0.00	\$75.00	Replace	/NRC
			STICKER 60KM/H	1.00	\$5.00	0.00	\$5.00	Replace	/NRC
6010295	Body	S06006-CW556	DOOR,ENGINE:REAR FRAME,FOR MAN A22 BUS	1.00	\$1,207.50	10.00	\$1,086.75	Replace	/BT
6010300	VE	36-25103-6000	LAMP,REVERSE (MAN BUS)	1.00	\$77.60	10.00	\$69.84	Replace	/CRA
6010323	Body	4000F06-HING735	HINGE:RH,REAR ENGINE DOOR,FOR MAN A22	1.00	\$138.00	10.00	\$124.20	Replace	XR
6010322	Body	4000F06-HING734	HINGE:LH,REAR ENGINE DOOR,FOR MAN A22	1.00	\$138.00	10.00	\$124.20	Replace	XR
6010371	Body	88-25215-0001	REFLECTOR,TRIM:FOR MAN BUS	1.00	\$77.60	0.00	\$77.60		/SCR
Total					\$10,387.70		\$9,439.51		

Added Spare Parts / Material Usage After Surveyor Signed off

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Repair dg - 5 days.
L/S.
After pump phras
Sun Pn (LKK)
12/11/2020



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 12/11/2020

User ID : GohKK2

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									