



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL

Ref : CS/AGI20012763/Uqf3q2

(BUDGET DIRECT INSURANCE)
190 CLEMENCEAU AVENUE #03-01
SINGAPORE SHOPPING CENTRESINGAPORE
239924

Date : 10-12-2020



Code : AGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJN 5867R	Veh. Inspected	SLK 7242Y
Policy No.		Coverage (\$)	0.00
Claim No.	C10008037/JM	Excess (\$)	0.00
Assign From	IVY RATILLA	Assign Date	19/11/2020

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ E 200 (A)	c.c	1796
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	WDD2120482A709912	Colour	GREY
Odometer	174084	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	235/40 ZR18	MICHELIN	6 mm
L/H Front Tyre	235/40 ZR18	MICHELIN	6 mm
R/H Rear Tyre	265/35 ZR18	MICHELIN	6 mm
L/H Rear Tyre	265/35 ZR18	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	19/11/2020	Inspection Date	20/11/2020
Survey held at	KY AUTO PTE LTD 25 KAKI BUKIT ROAD 4 #05-23 SYNERGY @ KB SINGAPORE 417800		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------