

ASS. REC. BY:

CS/

REF:

Smo/ 20012806/KV d3

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

CO/TP/WS/TP/RES/CO/RES/EVA/INV/INV

To inspect Vehicle No:

at Workshop on:

of

Insured: XE 5679Z

Policy No:

Claims No: CMTD2003402/AGC

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Est. or Market Value:

IDAC Accident Report

Consistent? : Yes or No

GIA / FR Spent:

Consistent? : Yes or No

Est. Repairs:

Lump Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng No:

GNO:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: N/A / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

31/5/21 Kenneth confirmed LS \$20,100 (Red 20,309.78,50%)

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2/6/21-Typist

Report Format: TP

Lump Sum H&B: (\$ 20,100

Days Of Repair: 16

Resurvey No. of Trip: 2

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation

\$ - RS. SI

Parking

Others

TOTAL

H C AUTO PTE LTD

160 Sin Ming Drive #05-09 Sin Ming Auto City Singapore 575722

Tel : 6457 0678 Fax : 6457 8287

Co. and GST Reg. No. : 200820153N

Date : 19 / 11 / 2020

ESTIMATE COSTS OF REPAIR

M/s Heng Leasing Pte Ltd
C/o 160 Sin Ming Drive
05-09 Sin Ming Auto City
Singapore 575722

Dear Sir / Madam ,

Vehicle no. : SMN 4129 J Honda Shuttle Hybrid 1.5
Accident date : 18 / 11 / 2020

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

NOT Authorized
21 Nov 20, 1.1.1

16-18 days

Quantity	Descriptions	Amount (S\$)
1	1 pc rear windscreen glass molding ✓	\$ -
2	1 pc rear quarter glass molding ✓	\$ -
3	1 pc tail gate ✓	\$ -
4	1 pc tail gate Honda Logo ✓	\$ -
5	1 pc tail gate 'SHUTTLE' emblem ✓	\$ -
6	1 pc tail gate "Hybrid" emblem ✓	\$ -
7	1 pc tail gate inner lock X	\$ -
8	1 pc o/s tail lamp ✓	\$ -
9	1 pc rear bumper fascia ✓	\$ -
10	1 pc n/s rear bumper reflector X	\$ -
11	1 pc n/s rear bumper reflector garnish X	\$ -
12	1 pc o/s rear bumper side retainer ✓	\$ -
13	2 pcs rear bumper bracket 1 @ ?	\$ -
14	2 pcs rear bumper sponge 1 @ X	\$ -
15	2 pcs rear bumper lower side garnish 1 @ ?	\$ -
16	1 pc o/s wheel house ?	\$ -
17	1 pc o/s rear fender ✓	\$ -
18	1 pc o/s rear fender inner garnish 2	\$ -
19	1 pc o/s rear fender outer garnish ✓	\$ -
20	1 pc o/s rear fender side bracket ✓	\$ -
21	2 pcs rear shock absorber 1 @ ?	\$ -
22	2 pcs rear hup bearing 1 @ ✓	\$ -
23	2 pcs rear axle beam 1 @ ✓	\$ -
24	4 pcs wheel cap 1 @ ✓	\$ -
25	1 pc rear exhaust box ✓	\$ -
26	1 pc rear exhaust box (center) ✓	\$ -
27	1 pc o/s rear door ✓	\$ -
28	2 pcs o/s rear door hinge 1 @ ✓	\$ -
	Balance C/FD	\$ -

H C AUTO PTE LTD

160 Sin Ming Drive #05-09 Sin Ming Auto City Singapore 575722

Tel : 6457 0678 Fax : 6457 8287

Co. and GST Reg. No. : 200820153N

Balance B/FD (SMN 4129 J)

\$ -

29	1 pc	o/s rear door checker	?	\$	-
30	1 pc	o/s rear door inner lock	?	\$	-
31	1 pc	o/s rear door rubber	X	\$	-
32	1 pc	o/s rear door inner trim board	?	\$	-
33	1 pc	o/s rear door glass regulator gear	?	\$	-
34	1 pc	o/s rear door glass regulator gear motor	?	\$	-
35	1 pc	o/s rear door blade sticker	✓	\$	-
36	1 pc	o/s front door	✓	\$	-
37	2 pcs	o/s front door hinge 1 @	X	\$	-
38	1 pc	o/s front door inner lock	?	\$	-
39	1 pc	o/s front door key lock	✓	\$	-
40	1 pc	o/s front door handle (outer)	✓	\$	-
41	1 pc	o/s front door rubber	?	\$	-
42	1 pc	o/s front door inner trim board	?	\$	-
43	1 pc	o/s front door outer moulding	X	\$	-
44	1 pc	o/s front door glass regulator gear	?	\$	-
45	1 pc	o/s front door glass regulator gear motor	?	\$	-
46	1 pc	o/s front door blade sticker	✓	\$	-
47	1 pc	o/s front door center pillar	X	\$	-
48	2 pcs	rocker panel garnish 1 @	✓	\$	-
49	1 pc	front bumper fascia	✓	\$	-
50	10 pcs	front bumper clip 1 @	✓	\$	-
51	1 pc	front bumper centre grille	?	\$	-
52	1 pc	front bumper lower cover	?	\$	-
53	1 pc	o/s front fender	X	\$	-
54	2 pcs	front fender inner garnish 1 @	✓	\$	-
55	20 pcs	front fender inner garnish clips 1 @	✓	\$	-
56	2 pcs	front fender "hybrid" emblem 1 @	✓	\$	-
57	2 pcs	front shock absorber 1 @	?	\$	-
58	2 pcs	front drive shaft 1 @	?	\$	-
59	2 pcs	front knuckle arm 1 @	✓	\$	-
60	2 pcs	front lower arm 1 @	✓	\$	-
61	1 pc	steering rack and pinion	✓	\$	-
62	2 pcs	front knuckle arm bearing 1 @	✓	\$	-
63	2 pcs	side link 1 @	?	\$	-
64	1 pc	anti roll bar	✓	\$	-
65	1 pc	fuel tank lower cover	X	\$	-
66	1 pc	engine lower cover center	✓	\$	-
67	2 pcs	engine side cover	✓	\$	-
68	2 pcs	front engine mounting 1 @	?	\$	-
		Balance C/FD		\$	-

H C AUTO PTE LTD

160 Sin Ming Drive #05-09 Sin Ming Auto City Singapore 575722

Tel : 6457 0678 Fax : 6457 8287

Co. and GST Reg. No. : 200820153N

Balance B/FD (SMN 4129 J)

\$ -

69 2 pcs rear engine mounting 1 @
70 1 pc front cross member

\$ -
\$ -
\$ -

Less 20%

\$ -
\$ -
\$ -

71 1 pc front no. plate ✓
72 1 pc rear panel inner seal x
73 3 4 pcs front & rear wheel rim 1 @ 650.00 P-7
74 4 pcs front & rear wheel tyre 1 @ 350.00 7
75 1 pc o/s rear quarter glass inner seal ✓
76 1 pc o/s rear quarter glass inner gum ✓
77 1 pc rear windscreen inner seal ✓
78 1 pc rear windscreen inner gum ✓

\$ 100.00 sn
\$ 250.00 sn
\$ 2,600.00 sn
\$ 1,400.00 sn
\$ 60.00 sn
\$ 60.00 sn
\$ 60.00 sn
\$ 60.00 sn
\$ 4,590.00

Labour charges
To putty and spray painting
To check, repair wiring
To check wheel alignment
Re-seal anti rust
Remove and refix engine mounting
Towing fee
Remove and refix o/s front & rear undercarriage
To transfer o/s front & rear door
To transfer tail gate
Remove and refix cushion seat, garnish, carpet
Remove and refix rear quarter glass
Remove and refix rear windscreen glass

\$ 2,800.00 1200l
\$ 3,600.00 2600l
\$ 120.00 40l
\$ 120.00 ✓
\$ 380.00 90l
\$ 180.00 7
(Bill) \$ 180.00 7
\$ 650.00 520l
\$ 240.00 120l
\$ 250.00 60l
\$ 350.00 120l
\$ 150.00 60l
\$ 150.00 120l

Plus : GST 7%

Sub-total

\$ 13,760.00
\$ 963.20
\$ 14,723.20



SINGAPORE POLICE FORCE



T/20201119/7009

1 of 3

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20201119/7009

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 19/11/2020 12:29		Vide Report No.:		Station Diary No.:	
Informant's Particulars					
Name of Informant: LEE KIM CHAN			Address: 317C ANCHORVALE ROAD #16-194 SINGAPORE 543317		
ID Type / ID No.: NRIC NO / S2581568H			Contact No.: Home/Office:		Mobile: 92334146
Nationality: SINGAPORE CITIZEN			Email: bruceleekimchan@gmail.com		
Sex: Male	Age: 56	Date of Birth: 21/08/1964	Type of Informant: Driver		
Race: Chinese		Language: English		Institution / School Name:	
Occupation: Chauffeur		Driving Licence Information: Class: 2B,3		Date of Expiry:	

General Information of the Accident				
Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 18/11/2020 16:05	Type of Location: Y-Junction
Location: CRAWFORD STREET				
Weather: Clear		Road Surface: Dry	Road Speed Limit: 60 Km/h	
Traffic Flow: One Way		Traffic Control: Traffic Light - Working		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Conditio	No of
SMN4129J	Car	HONDA	SHUTTLE	Blue	Seriously Damaged	1
XE5679Z	Lorry	MAN	TGS	White	Slightly Damaged	0



**SINGAPORE
POLICE FORCE**



T/20201119/7009

2 of 3

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20201119/7009

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SMN4129J	AIG ASIA PACIFIC INSURANCE PTE. LTD.	999993872	25/02/2020	24/02/2021

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	LEE KIM CHAN	ID No.	S2581568H
Related Vehicle	SMN4129J (Car)	Contact No.	92334146
Hospital/Clinic	HORIZON MEDICAL CENTRE	Class of Driving Licence & Expiry	Class: 2B,3 Date of Expiry: NIL
Date	19/11/2020	Date	19/11/2020
No. of Days granted Medical Leave	03	Degree of	Serious

Brief Details.


ON 18/11/2020 AT ABOUT 1605HRS, WHILE I WAS DRIVING MY MOTOR VEHICLE A SMN 4129J ALONG CRAWFORD STREET AT THE 2ND LANE FROM THE LEFT, HEADING TO BEACH ROAD.

KEEPING WITHIN MY LANE, WHEN I CROSSED OVER THE BRIDGE OF ROCHOR RIVER, SUDDENLY A MOTOR VEHICLE B XE 5679Z, WHICH WAS DRIVING ON MY RIGHT LANE, HE TRYING TO CHANGED HIS LANE TO MY LANE AND HIS FRONT LEFT PORTION HIT ONTO THE LEFT PORTION OF MY VEHICLE A. THE IMPACT WAS GREAT AND PUSHED MY VEHICLE A TO SKID AND LOST CONTROL AND HIS FRONT PORTION HIT MY RIGHT PORTION AGAIN WHEN MY VEHICLE A LOST CONTROL AND CAUSED MY VEHICLE A CROSSED OVER THE CENTER ROAD KERB AND LANDED ON THE OPPOSITE DIRECTION.

MY VEHICLE A WAS SERIOUS DAMAGED AND I HAVE ONE GRAB'S PASSENGER, MR ALBERT ONBOARD.

ON 19/11/2020 I FELT MY NECK AND BACK PAIN, I GO AND VISITED DOCTOR AND I GOT 3 DAYS MC.

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to police report attached T20201119/7009.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

GIARMC SketchPlanForm_V3

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	
Owner ID:	Company 603E
Vehicle No.:	SMN4129J
Vehicle to be Exported:	Yes
Intended Deregistration Date:	19 Nov 2020
Vehicle Make:	HONDA
Vehicle Model:	SHUTTLE HYBRID 1.5 AUTO
Primary Colour:	Blue
Manufacturing Year:	2019
Engine No.:	LEB7112250
Chassis No.:	GP72009810
Maximum Power Output:	101.0 kW (135 bhp)
Open Market Value:	\$21,708.00
Original Registration Date:	07 Aug 2019
First Registration Date:	07 Aug 2019
Transfer Count:	0
Actual ARF Paid:	\$12,392.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	06 Aug 2029
PARF Rebate Amount:	\$9,294.00
COE Expiry Date:	06 Aug 2029
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$35,906.00
COE Rebate Amount:	\$28,724.00
Total Rebate Amount:	\$38,018.00

The information contained herein is correct as at 19 Nov 2020

OK